Trial	Dep.		
Exhibit No.	Exhibit No.	Deponent	Title
1	100	Agg	Chemistry and Enviroment Group monthly report - April 1995, by J.R. Harlamovs
2	102	Agg	Memo from Duncan to Kenyon re: Toxicity Assessment of Cominco Outfalls
3	103	Agg	Toxicity Memo - Distribution List (Toxicity Assessment of Cominco Outfalls
4	108	Agg	"Trail Operations at 100 Still Ahead of the Curve," in Canadian Mining Journal
5	109	Agg	Memo re: slag leachability: highlights of the meeting with consultant Dr. DA Brosnon, 8/5/92
6	113	Agg	Memo re: Permit Excursions
7	54	Ball	Effluent Management Task Force Meeting Minutes - December 3, 13, 1991, by Kuit
8	55	Ball	Effluent Management Task Force Meeting Minutes - January 21, 1992
9	56	Ball	Effluent Management Task Force Meeting Minutes - February 17, 1992, by Kuit
10	57	Ball	Memo: ETP Expansion
11	58	Ball	Research Memo: Trail Operations Effluent Recycle and Reduction
12	59	Ball	Research Report: Metals Removal from 07 Sewer, by McKay
13	61	Ball	Effluents & Water Quality / June 1994 Presentations
14	63	Ball	Chemical Process Research Monthly Report - December 1990, by Ball
15	65	Ball	Slag Study / Scope of Environment Related Work
16	68	Ball	Memo from Ball to Kuit: Mercury Removal Possibilities
17	70	Ball	Memo: The Effluent Treatment Plant as a Special Waste Facility
18	71	Ball	Effluent Management Task Force Minutes of Meeting / May 15, 1992
19	276	Beatty Spence	BC ELP - Information Issue: Mercury Spills to Columbia, Sept 30 -Oct 1 & Oct 1-2 1992, prepared by Beatty Spence
20	277	Beatty Spence	Mercury Spill - Oct 1, 1992, Report to Crown Council, prepared by Len Butler
21	278	Beatty Spence	Memo from Beatty Spence to L. Butler re Environmental Impact Assessment - Cominco Hg Spill, 10/1/92
22	279	Beatty Spence	Cominco File Note re Meeting with Carl Johnson / 9/6/95
23	280	Beatty Spence	Memo from Beatty Spence to L. Butler re Cominco Spill from Sewer II Dec 9/10, 1993
24	281	Beatty Spence	Memo from Beatty Spence to Butler and Johnson re Zinc Slurry Spill, July 23, 1997
25	282	Beatty Spence	Columbia River 1991/93, Integrated Environmental Monitoring Program, Public Report
26	284	Beatty Spence	CRIEMP 1991/1993 Interpretive Report by Aquametrix Research Ltd. Dup???
27	1481	Bierman	River Mile Table for the Upper Columbia River and Lake Roosevelt Including U.S. EPA and USGS River Miles, Location and Landmark Descriptions, and RI/FS Work
27	1401	Diciman	Plan Reach Segment Definitions, Table 1, page 37, Expert Report of Victor J. Bierman, Jr., September 17, 2010
28	1481	Bierman	Estimated Critical Boundary Shear Stresses to Initiate Erosion for Various Size Fractions of Granulated Slag, Table 2, page 43, Expert Report of Victor J. Bierman, Jr.,
			September 17, 2010
29	1481	Bierman	Map of Upper Columbia River and Lake Roosevelt, Figure 1, page 47, Expert Report of Victor J. Bierman, Jr., September 17, 2010
30	1481	Bierman	Map of Canadian Portion and Northern Section of the U.S. Portion of the Upper Columbia River and Lake Roosevelt, Figure 2, page 48, Expert Report of Victor J.
			Bierman, Jr., September 17, 2010
31	1481	Bierman	Map of the Canada Reach of the Upper Columbia River and Lake Roosevelt, Figure 3, page 49, Expert Report of Victor J. Bierman, Jr., September 17, 2010
32	1481	Bierman	Map of the Northport Reach of the Upper Columbia River and Lake Roosevelt, Figure 4, page 50, Expert Report of Victor J. Bierman, Jr., September 17, 2010
33	1481	Bierman	Map of the Upper Reservoir Reach of the Upper Columbia River and Lake Roosevelt, Figure 5, page 51, Expert Report of Victor J. Bierman, Jr., September 17, 2010
34	1481	Bierman	Map of the Middle Reservoir Reach of the Upper Columbia River and Lake Roosevelt, Figure 6, page 52, Expert Report of Victor J. Bierman, Jr., September 17, 2010
35	1481	Bierman	Map of the Lower Reservoir Reach of the Upper Columbia River and Lake Roosevelt, Figure 7, page 53, Expert Report of Victor J. Bierman, Jr., September 17, 2010
36	1481	Bierman	Map of Locations of Dams in the Upper Columbia River System and Lake Roosevelt, Figure 8, page 54, Expert Report of Victor J. Bierman, Jr., September 17, 2010
37	1481	Bierman	Map of Locations of Dams in the Upper Columbia River System in the Vicinity of the International Border, Figure 9, page 55, Expert Report of Victor J. Bierman, Jr., September 17. 2010
38	1481	Bierman	Water Column Total Zinc Concentrations Associated with Spill Event on April 7, 2008, at the Teck Cominco facility at Trail, British Columbia. Ambient Concentrations
		5.51111011	Upstream at Birchbank (top panel), Ambient and Spill Event Concentrations Downstream at Waneta (middle panel) and Spill Event Concentrations at Waneta on an
			Upstream at Birchbank (top panel), Ambient and Spill Event Concentrations Downstream at Waneta (middle panel) and Spill Event Concentrations at Waneta of Lexican Spill Event Concentrations at Lexican Spill Event Concentration Spill Event Concentrations at Lexican Spill Event Concentration Spill Event

Map of Surface Sediment Total Zinc Concentrations for 1996-2007, Figure 34, page 80, Expert Report of Victor J. Bierman, Jr., September 17, 2010

Surface Sediment Total Lead Concentrations by River Mile for 1984-1995, Figure 35, page 81, Expert Report of Victor J. Bierman, Jr., September 17, 2010

62

63

1481

1481

Bierman

Bierman

age 82, Expert Report of Victor J. Bierman, Jr., September 17, 2010 3, Expert Report of Victor J. Bierman, Jr., September 17, 2010 3, Expert Report of Victor J. Bierman, Jr., September 17, 2010 39, page 85, Expert Report of Victor J. Bierman, Jr., September 17, 2010 40, page 86, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 87, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 88, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 88, Expert Report of Victor J. Bierman, Jr., September 17, 2010 or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 43, page 89, or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 44, page 90, ons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page nan, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010 6 for 2003-2009, Figure D-1, page D-1, Expert Report of Victor J. Bierman, Jr.,
3, Expert Report of Victor J. Bierman, Jr., September 17, 2010 4, Expert Report of Victor J. Bierman, Jr., September 17, 2010 39, page 85, Expert Report of Victor J. Bierman, Jr., September 17, 2010 40, page 86, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 87, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 88, Expert Report of Victor J. Bierman, Jr., September 17, 2010 gr 88, Expert Report of Victor J. Bierman, Jr., September 17, 2010 gr 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 43, page 89, por 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 44, page 90, pons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page pan, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
A, Expert Report of Victor J. Bierman, Jr., September 17, 2010 39, page 85, Expert Report of Victor J. Bierman, Jr., September 17, 2010 40, page 86, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 87, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 88, Expert Report of Victor J. Bierman, Jr., September 17, 2010 gr 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 43, page 89, or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 44, page 90, ons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page nan, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
39, page 85, Expert Report of Victor J. Bierman, Jr., September 17, 2010 40, page 86, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 87, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 88, Expert Report of Victor J. Bierman, Jr., September 17, 2010 gr 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 43, page 89, or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 44, page 90, ons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page man, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
40, page 86, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 87, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 88, Expert Report of Victor J. Bierman, Jr., September 17, 2010 or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 43, page 89, or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 44, page 90, ons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page man, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
ge 87, Expert Report of Victor J. Bierman, Jr., September 17, 2010 ge 88, Expert Report of Victor J. Bierman, Jr., September 17, 2010 or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 43, page 89, or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 44, page 90, ons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page man, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
ge 88, Expert Report of Victor J. Bierman, Jr., September 17, 2010 or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 43, page 89, or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 44, page 90, ons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page nan, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 43, page 89, or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 44, page 90, ons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page nan, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 43, page 89, or 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 44, page 90, ons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page nan, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
ons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page nan, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
ons for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure 45, page nan, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
nan, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
nan, Jr., September 17, 2010 of Victor J. Bierman, Jr., September 17, 2010 7, 2010
of Victor J. Bierman, Jr., September 17, 2010 7, 2010
of Victor J. Bierman, Jr., September 17, 2010 7, 2010
7, 2010
for 2003-2009, Figure D-1, page D-1, Expert Report of Victor J. Bierman, Jr.,
or 1983-1985 (top panel) and 2003-2009 (bottom panel), Figure D-2, page D-2,
s for 2003-2009, Figure D-3, page D-3, Expert Report of Victor J. Bierman, Jr.,
or 1983-1985 (top panel) and 2003-2009 (bottom panel), Figure D-4, page D-4,
ns for 1983-1985 (top panel) and 2003-2009 (bottom panel), Figure D-5, page D-
ns for 1363-1363 (top parier) and 2003-2003 (bottom parier), Figure D-3, page D
ons for 1996-2007, Figure E-1, page E-1, Expert Report of Victor J. Bierman, Jr.,
510 101 2330 2007) 1.18410 2 2, page 2 2, expert rioport of viocol 31 Biolinaily 11,
s for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure E-2, page E-
ions for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure E-3, page
s for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure E-4, page E-
itions for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure E-5,
ns for 1984-1995 (top panel) and 1996-2007 (bottom panel), Figure E-6, page E-
. 2000 C
t. 2009 Sampling Campaign, Figure 1, page 5, Expert Report of Joel D. Blum,
May 2010 Sampling Campaign, Figure 2, page 6, Expert Report of Joel D. Blum,
way 2010 Samping Campaign, Figure 2, page 0, Expert Report of Juli D. Blum,
Sampling Campaign, Figure 3, page 7, Expert Report of Joel D. Blum, May 11,
, Jamping Campaign, rigare 3, page 7, Expert Report of Joer D. Bialli, May 11,
e. Figure 4, page 9, Expert Report of Joel D. Blum. May 11, 2011
e, Figure 4, page 9, Expert Report of Joel D. Blum, May 11, 2011
e, Figure 4, page 9, Expert Report of Joel D. Blum, May 11, 2011 gn, Figure 5, page 10, Expert Report of Joel D. Blum, May 11, 2011 d' Samples as a Function of River Mile, Figure 6, page 11, Expert Report of Joel
n n

PageID.28513 Page

Trial	Dep.		
Exhibit No.		Deponent	Title
94	1480	Blum	All Individual Samples Analyses and Average Values for Unfiltered Hg for the Sept Oct. 2009 Sampling Campaign, Figure 7, page 12, Expert Report of Joel D. Blum,
J-1	1400	blum	May 11, 2011
95	1480	Blum	Plot of the Amount of Zn Released as a Function of Time from the Data Presented in Paulson et al. (2006) for Sediment Core Incubation LR-6, Figure 8, page 19,
			Expert Report of Joel D. Blum, May 11, 2011
96	1480	Blum	Replication of Figure 27 from Riese (2011) with the Addition of the Orange Arrow Showing a Two Order of Magnitude Uncertainty in Zn Fluxes Based on the
			Incubation Experiments of Paulson et al. 2006), Figure 9, page 19, Expert Report of Joel D. Blum, May 11, 2011
97	1480	Blum	Plots of Surface Water Data for the Upper Columbia River from Surface Water Data Summary and Data Gap Report, Appendix B, page 32, Expert Report of Joel D.
00	NI O	DI	Blum, May 11, 2011
98	NA	Blum	Resume of Joel Blum
99	NA	Blum	CCT Expert Blum, Joel\5-11-11 Report\J Blum Docs Considered\Queneau 2011.rtf
100	NA 10 I NAI	Blum	CCT Expert Blum, Joel\5-11-11 Report\J Blum Docs Considered\USEPA 1631-1.pdf
101	19 LMI	Brown	Letter from BA Heskin/Environment Canada to R.H. Ferguson/BC Ministry of Environment re Concern Developing at Cominco re recent acid spills
102	21 LMI	Brown	Letter from EN Doyle to DA MacCullouch re suggested changes to Geoffrey TG Scott's report on his Environmental Risk Analysis
103	297	C. Johnson	Notes from Meeting with W.M.B. re Acid Discharge Sampling Survey, by Kenyon
104	298	C. Johnson	Memo from C. Johnson to file re Meeting 5/23/84, Mercury Balance Zinc Roaster Circuit
105	299	C. Johnson	Memo from C. Johnson to D. McDonald re Cominco Court Case, Mercury Spill of March 1980
106	300	C. Johnson	Status of Mercury in Fertilizer Plant Effluent, Meeting 8/16/1989, by Johnson
107	301	C. Johnson	Minister's Briefing Note
108	302	C. Johnson	Memo from R.J. Hammond to Carl Johnson re Cominco Waste Permits
109	303	C. Johnson	Memo from C. Johnson to Ken McLennan re Cominco Spill of 4/10/1991
110	304	C. Johnson	Presentation by C. Johnson, Columbia River Water Quality Seminar Oct 8,9, 1991
111	305	C. Johnson	Letter from C. Johnson to Graham Kenyon re Your FAX of Jan 27, 19924:00 pm / Slag Commitment
112	307	C. Johnson	Letter from C. Johnson to Kenyon re Frequency of Phosphoric Acid Spills at Fertilizer Plant
113	308	C. Johnson	Letter from C. Johnson to Roger Watson re Cominco Commitment to a Revised Slag Program
114	311	C. Johnson	Letter from C. Johnson to Doug Glover re Monitoring Results for March and April 1995
115	312	C. Johnson	Memo to File PE/2753 re C. Johnson and B. Duncan float down river to observe slag accumulation on beaches and sandbars between smelter to the border
116	227	Cox	Electronic microscopic photos of slag
117	228	Cox	Concentrations of Elements in Sediments and Selective Fractions of Sediments, and in Natural Waters in Contact with Sediments from Lk. Roosevelt, 9/04, by USGS
118	229	Cox	Release of elements to Natural Water form Sediments of Lk. Roosevelt, published in Environmental Toxicology and Chemistry, Vo. 26, No. 12, pp. 2550/2559
119	1201	Cox	Microlab NW Laboratory report to Hurst re Slag in Sediment Analysis
120	1202	Cox	Draft Sediment Quality Assessment of LR, 1992 by USGS/EPA, Water/Supply Paper
121	1207	Cox	Sediment-Quality Assessment of FDR Lake and the Upstream Reach of the Columbia River, 1992
122	1208	Cox	Preliminary Scope of Work: Assessment of Trace/element concentrations in sediment cores and rates of sediment accumulation in Lake Roosevelt
123	1216	Cox	Occurrence of trace elements and metallurgical slag in cores from LR
124	287	Crozier	Memo from R. Crozier to file re Minutes of Meeting with US DOI in Grand Coulee, WA, June 23, 1981
125	288	Crozier	File Note by G.F. Kenyon re Visit by John Haller/National Park Svc and Frank Madison/Bureau of Reclamation, on May 6, 1986
126	289	Crozier	Memo from Carl Johnson to Crozier re December 1994 Cominco Permit Non-Compliances
127	290	Crozier	Report by SIGMA Engineering Ltd / Columbia River Integrated Environmental Monitoring Program
128	291	Crozier	File Note by G.F. Kenyon re TelCon with R. Crozier, WMB, Nelson, Jan 29, 1990
129	292	Crozier	Memo from Crozier to Jane Ramin re: Cominco Ltd. Trail Potential Cleanup Requirements
130	293	Crozier	Letter from G.F. Kenyon to R. Crozier re Permits: Annual Discharge Limits
131	294	Crozier	Significant Event Supplementary Report re deliberate discharge of mercury laden sludge (6000+ lbs of mercury) on March 19-20, 1980
132	295	Crozier	Memo from Crozier to R. Daloise re Cominco Permit Exceedance - June 7, 1994
133	296	Crozier	Table of Signifiant Noncompliance Evaluation of Waste Management Permits, Approvals and Order
134	1	Diefenbach	Diefenbach Report: Columbia Basin Mine and Mill Tailings Supplemental Sampling Program , September 2010
135	2	Diefenbach	Diefenbach Report: Darft Upper Columbia River Sampling and Analysis 2002-2010, Field and Laboratory Activities
	i-	Dicicioacii	Section 2011 Tepor Country of the Country of the American State of the Country of

Trial	Dep.		
Exhibit No.		Deponent	Title
136	4 LMI	Downie	Letter from Pollution Control Branch to EN Doyle: "the use of the Columbia River, notwithstanding its huge dilution potential, should not be considered as a waste
130		Downie	disposal site."
137	223	Duncan	Cominco's 1995 Columbia River and Effluent Monitoring Program, by Duncan
138	224	Duncan	Environmental Performance Review of the New KIVCET Lead Smelter and Elimination of Slag Discharge: Assessment of Columbia River Receiving Waters, Summary
139	225	Duncan	Assessment of Columbia River Receiving Waters, Final Report
140	226	Duncan	Golder Associates Draft Report on Sequential Extraction of Columbia River Sediments
141	227	Duncan	Report on the Sequential Analysis of Lines of Evidence for Risk from the Teck Cominco Smelter at Trail, BC
142	230	Duncan	Columbia River Travel Time Model Assessment, by Duncan
143	231	Duncan	Environmental Impact of Accidental Discharge of ZPL Fume by TCML to the Columbia River via Comb III Outfall on April 7, 2008 by Duncan for Robyn Roome
144	235	Duncan	Group of documents from Duncan's files. Last page: Proposed River Slag Study
145	238	Duncan	Briefing Note by Duncan re Lake Rosevelt USGS/CCT Trace Elements in Sediments (Cox, et al 2005) and Rick Cardwell's proposed studies
146	243	Duncan	Photos of Slag Grains
147	244	Duncan	Memorandum from Duncan to Derrill Thomas re slag and coal discharges to the River as per suggested revisions
148	245	Duncan	Email from Duncan to Colin Spence and others re: Brief History of Major Changes at Teck Cominco Smelter Trail - Sort of brief but a lot happens around here
149	246	Duncan	Email string between Scott Becker, Marko Adzic & Todd Martin re fingerprinting, with table re estimate of metals to river via slag discharge
150	248	Duncan	Email string between Duncan, Gloria Armstrong and Cox re slag releases to Columbia River Chart in your presentatioNAqueous Geo chemistry course with USGS
151	249	Duncan	Memorandum from Duncan to Derrill Thomas re Toxicity Testing of Slag Discharge during Tapping
152	250	Duncan	Memorandum from Duncan to distribution list re Toxicity Assessment of Cominco Outfalls
153	251	Duncan	Memorandum from Duncan to Horswill re brief for your meeting (March 11) with Louis Tousignant
154	253	Duncan	Email string between Duncan & Kuit re: Sediment Trend Analysis - Slag in the Columbia (Also Kuit 27)
155	255	Duncan	Briefing Note by Duncan re Lake Rosevelt USGS/CCT Trace Elements in Sediments (Cox, et al., 2005)
156	257	Duncan	Spreadsheets of slag production estimates from Pb production data (from annual reports), calculated slag to river and measured slag to river, from 1910/1997;
			Comparison of slag calculated based on Pb produced as compared to slag determined by metallurgical balance
157	259	Duncan	Spreadsheet re Estimate of metals to river via slag discharge
158	123	Edwards	Cominco File Note re: Summary - 1997 Trail Operations Spills
159	124	Edwards	Cominco Reported Spills May 97 table
160	129	Edwards	Effluent Management Plan, Cominco Trail Operations
161	4 LMI	Edwards	Abstract of investigation of undissolved mineral matter in Columbia River at Northport, WA. "The Columbia River, both above and below Northport, was found to be
162	6 LMI	Edwards	polluted with small black particles of smelter slag." Decision of the Tribunal Reported March 11, 1941, Trail Smelter Arbitration between US and Canada
163	8 LMI	Edwards	Chemistry in Canada, Environmental Control at Cominco Ltd., by Nigel Doyle
164	NA	Edwards	Appendix 42, Slag Pollution, Appendices to the Answer & Argument Presented in Behalf of the US to the Canadian Agent
165	82 LMI	Fletcher	The Environmental Effect of Trail Slag on the Columbia River " Cominco's position that tail slag is harmless cannot be defended with any degree of objectivity."
166	88 LMI	Glover	1988 Environmental Report, Trail Operations, by Kenyon, McCunn, & Glover
167	140	Horswill	1993 Environmental Report, Trail Operations, by Glover
168	148	Horswill	Letter to Cathy McGregor and Christine Stewart from Horswill re: Water Quality Objectives for Lower Columbia
169	159	Kenyon	1988 Environmental Report, Trail Operations, by Kenyon, McCunn & Glover
170	160	Kenyon	1989 Environmental Report, Trail Operations, by Kenyon, McCunn & Glover
171	161	Kenyon	Letter from Department of State to the Embassy of Canada re mercury discharge into the Columbia on 3/19-22/1980
172	162	Kenyon	Letter from Canadian Embassy to Department of State re mercury discharge into the Columbia on 3/19-20/1980
173	163	Kenyon	Significant Event Report re deliberate discharge of 6000-7000 lbs. (mercury) sludge on 3/19-20/1980
174	164	Kenyon	Technical Report by BC Environment for Cominco's application for permits
175	165	Kenyon	The environmental renaissance of a smelter, by Kenyon

PageID.28515 Page

Trial	Dep.		
Exhibit No.	Exhibit No.	Deponent	Title
176	166	Kenyon	Slag Disposal Options Environmental and Engineering Studies
177	167	Kenyon	Environmental Briefing Notes, Trail Lead Study by Kenyon
178	168	Kenyon	File Note by Kenyon re Meeting with Columbia River Study Steering Committee Oct 15, 1990 with Waste Management Branch Permits meetings with Carol Johnson,
		,	11/28 and 12/4/1990
179	171	Kenyon	File Note by Kenyon re Meeting April 11, 1991 - Slag Disposal
180	172	Kenyon	Memorandum from Kenyon re Slag Disposal
181	173	Kenyon	Letter from Kenyon to Jim McLaren re Permit PE-02753 - Trail Slag Disposal
182	174	Kenyon	Letter from Jim McLaren to Kenyon re Permit PE-02753 - Trail Slag Disposal
183	175	Kenyon	Slag Study - Scope of Environment Related Work, by Kuit
184	176	Kenyon	The Question of Tail Slag Disposal to the Columbia River, by Kenyon
185	NA	Kenyon	The Question of Tail Slag Disposal to the Columbia River, by Kenyon, with Tables 1, 2 & 3 attached (authenticated by Kenyon at Dep. Ex. 176)
186	177	Kenyon	Trail Metallurgical Operations Application for Extension of Effluent Permit PE/02753
187	182	Kenyon	Letter from Leslie Churchland to Crozier re amended permits pursuant to the Waste Management Act on behalf of Cominco Ltd. issued Feb 14, 1992
188	186	Kenyon	Memorandum from Kenyon to Watson re expedited slag option
189	187	Kenyon	Tail Slag Fact Sheet (Draft), faxed 7/29/1992
190	191	Kenyon	Memorandum from Kenyon re III combined performance: Hg
191	192	Kenyon	Email from Kenyon to "Bob" re slag storage
192	193	Kenyon	Email string between Kenyon and Hilts re Lake Roosevelt, 4/23/2003 and 4/30/2003
193	NA	Kern	Kern Documents Considered\Data\KernAnalysis Figures SR8 to SR12.xlsx
194	1442	Kern	Correlations between reported principal component scores from Dr. Riese's expert witness report and calculated principal component scores based on the same
134	1442	Kem	data, Table 1, page 8, Expert Report of J, Kern, May 13, 2011
195	1442	Kern	Correlation between principal components extracted by Riese from the full metals data set and those extracted by Kern from the EPA/CH2MHill and Hazen studies,
133	1442	Kerri	Table 2, page 9, Expert Report of J, Kern, May 13, 2011
196	1442	Kern	Description of parameters used in estimating rock retained in Lake Roosevelt as a function of ore produced by underground mines in the United States, Table 3, page
			15, Expert Report of J, Kern, May 13, 2011
197	1442	Kern	Summary of bootstrap distributions of waste rock retained in Lake Roosevelt (1000 tons) for Mr. Brown's coefficients assuming no error, and 10%, 20%, and 30%
			relative error in the coefficients, Table 4, page 24, Expert Report of J. Kern, May 13, 2011
198	1442	Kern	Comparison of principal component scores reported by Riese to factor scores reported by Vlassopoulos in their expert reports, Figure 2, page 6a, Expert Report of J,
			Kern, May 13, 2011
199	1442	Kern	Plots of first two component scores for EPA/CH2MHill study based on scores extracted from the full data set by Riese and those extracted from the EPA/CH2MHill
			and Hazen, Figure 2, page 10, Expert Report of J, Kern, May 13, 2011
200	1442	Kern	Log-log relationship between ore and waste rock produced for 55 underground mines in the United States, Figure 3, page 17, Expert Report of J, Kern, May 13, 2011
201	1442	Kern	Bootstrap distribution of estimated regression between ore and waste rock production and cumulative distribution of 393 underground mines in the United States
			included in Mr. Brown's analysis and for which ore production is known, Figure 4, page 18, Expert Report of J, Kern, May 13, 2011
202	1442	Kern	Total soil loss from waste piles plotted against total waste rock produced for 393 underground mines, as reported by Mr. Brown, Figure 5, page 20, Expert Report of
			J, Kern, May 13, 2011
203	1442	Kern	Bootstrap uncertainty distribution of Mr. Brown's estimate of waste rock from U.S. underground mines retained in Lake Roosevelt, Figure 6, page 21, Expert Report
204	1112		of J, Kern, May 13, 2011
204	1442	Kern	Bootstrap uncertainty distribution of Mr. Brown's estimate of waste rock from U.S. underground mines retained in Lake Roosevelt, with 10%, 20% and 30% relative
205	1442	Kern	error in model parameters, Figure 7, page 25, Expert Report of J, Kern, May 13, 2011 Resume of John W. Kern, Attachment A, page 29, Expert Report of J, Kern, May 13, 2011
206	1447	Kuit	Effluent Management Task Force - Meeting Minutes - March 13, 1992, by Kuit
207	4		
207	4	Kuit	The Sun Newspaper Article: "Present Discharge Levels not a Threat"
	5	Kuit	Lower Columbia River Distribution of Slag and the Impact on Fish Habitat, by Sigma Engineering
209	6	Kuit	Sediment Quality Assessment of Franklin D. Roosevelt Lake and the Upstream Reach of the Columbia River, Washington, 1992, by USGS
210	/	Kuit	Slag Study - Environmental Components - Minutes of Meeting - July 12, 1991, by Kuit
211	8	Kuit	Cominco Research Project Definition Worksheet

PageID.28516 Page

Trial Exhibit No.	Dep. Exhibit No.	Deponent	Title
212	9	Kuit	Memo: Disposal of Granulated Tail Slag in Columbia River, from PJ McIver
213	11	Kuit	Letter from Doyle re Geoffrey T.G. Scott's report on his Environmental Risk Analysis
214	13	Kuit	File Note by Doyle: Review of Trail Operations' Environmental Control Permit Situation
215	17	Kuit	Notes from meeting with W.M.B. Re Acid Discharge Sampling Survey
216	18	Kuit	Notes from meeting with W.M.B. Re Acid Discharge Sampling Survey
217	22	Kuit	Memo by Kuit: Environmental Component of Slag Study - Interium Results (Also McKay 71 in Teck v. LMI case)
218	23	Kuit	Effluent Management Task Force - Meeting Minutes - November 7, 1991, by Kuit
219	24	Kuit	Fax from McCandless to Kuit and Kenyon re total & dissolved metals in test
220	28	Kuit	E-mail between Kuit and Duncan: Mercury in Atmosphere and other issues (Also Kuit 131 in Teck v. LMI)
221	29	Kuit	Memo from Kuit to Kenyon re: Slag Disposal Permit Application - Terms of Reference
222	146 LMI	Kuit	Teck Memo from PJ McIver to Kenyon re DJ McKay's Report: "Metals Related Environmental Assessments of Disposal Options for Fuming Furnace Slag"
223	149 LMI	Kuit	Dames & Moore Report, Investigation of Geotechnical and Environmental Issues Proposed Land Disposal for Fuming Furnace Tail Slag, Duncan Flats, B.C.
224	155 LMI	Kuit	Memo from SJ Walden to Gord Mattson re Interim Report-Laboratory Column Leaching of Ferrous Granules
225	2 LMI	Kuit	Excerpt: "Abstract of US Opening Statement," from Trail Smelter Question: Part I Abstract & Analysis of US Statement & Reply and Appendices Thereto; Part 2
			Material Prepare for Canadian Counsel for Argument, by RC Crowe
226	3 LMI	Kuit	Appendices to the Answer & Argument Presented in Behalf of the US to the Canadian Agent (excerpts)
227	4 LMI	Kuit	Excerpt: "Slag Pollution of the Columbia River," from Trail Smelter Question: Part I Abstract & Analysis of US Statement & Reply and Appendices Thereto; Part 2
			Material Prepare for Canadian Counsel for Argument, by RC Crowe
228	200	Magoon	BC Environmental Permit PE-02753 (effluent)
229	201	Magoon	New Lead Smelter Project - Review of Environmental Effects on Trail Operations
230	208	Magoon	Risk Assessment Trail Operations Cominco Ltd. 2000
231	215	Magoon	Statement of Certification/Summary of Data Submitted re: Trail Operations Releases
232	1238	Majewski	Concentrations and Distribution of Slag-Related Trace Elements and Mercury in Fine-Grained Beach and Bed Sedimentsof Lake Roosevelt, April-May 2001
233	30	McKay	Metals-Related Environmental Assesments of Disposal Options for Fuming Furnace Slag (Also McKay 63 in Teck v. LMI)
234	31	McKay	Memo: Water Leach Slag Studies (Also McKay 66 in Teck v. LMI)
235	32	McKay	File Note: Leachability of Tail Slag
236	33	McKay	Memo from McKay to Kenyon: Leachability of Blast Furnace Slags in SWEP Testing
237	34	McKay	Memo from McKay to Kuit: Background Data on Cominco Research Testwork for Hydrogeotechnical Consultants
238	35	McKay	Research Report by McKay: Metals-Related Aspects of Land Disposal of Furning Furnace Slag
239	36	McKay	Memo: Slag Leachability: Highlights fo the Meeting with Consultant DR. D.A. Bronson, August 5, 1992
240	37	McKay	Memo from McKay to Kuit and Kenyon: Update on Cominco Research Testwork on "Metals-Related Issued of Land Disposal of Furning Furnace Slag"
241	64 LMI	McKay	Kootenay Air and Water Quality Study, Phase I, by Ministry of Environment (excerpts)
242	65 LMI	McKay	Kootenay Air and Water Quality Study, Phase II, by Ministry of Environment (excerpts)
243	68 LMI	McKay	File Note by DG Reynolds: Leachability of Tail Slag
244	70 LMI	McKay	Environmental Characterizaton of Fuming Furnace Slag
245	72 LMI	McKay	Slag Disposal Options, Environmental and Engineering Studies
246	NA	McLean	CCT v Teck\CCT Expert McLean, Dave (NHC)\9-17-10\ Report\Modeling\0.25mm Particles.gif
247	NA	McLean	CCT Expert McLean, Dave (NHC)\9-17-10\ Report\Modeling\1mm Particles.gif
248	NA	Mc Lean	CCT Expert McLean, Dave (NHC)\9-17-10 Report\NHC Supporting Documents\Field data collection\Underwater Video\cobble wt slag wanetaeddy.avi
249	NA	McLean	CCT Expert McLean, Dave (NHC)\9-17-10 Report\NHC Supporting Documents\Field data collection\Underwater Video\sand wt slag wanetaeddy.avi
250	NA	McLean	CCT Expert McLean, Dave (NHC)\9-17-10 Report\NHC Supporting Documents\Photos\2010 0304.zip\seweroutfall trailersalesyard.jpg
251	NA	McLean	CCT Expert McLean, Dave (NHC)\9-17-10 Report\NHC Supporting Documents\Photos\Slag Photos.zip
252	1440	McLean	Summary of Field Investigations conducted by NHC, Table 1, page 3, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International
		Wickeri	Boundary, Northwest Hydraulic Consultants, September 17, 2010
253	1440	McLean	Period of Record of Key Hydrometric Stations, Table 2, page 4, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
254	1440	McLean	Period of Record of Sediment Stations, Table 3, page 7, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010

Trial	Dep.		
Exhibit No.	Exhibit No.	Deponent	Title
255	1440	McLean	Period of Record of Water Quality Stations, Table 4, page 7, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International
			Boundary, Northwest Hydraulic Consultants, September 17, 2010
256	1440	McLean	Comparison of Discharges Before and After Flow Regulation, Table 5, page 12, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to
			International Boundary, Northwest Hydraulic Consultants, September 17, 2010
257	1440	McLean	Historical Suspended Sediment Data Summary – Columbia River at Birchbank (08NE049), Table 6, page 13, Opinion on the Transport of Metallurgical Slag by the
			Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
258	1440	McLean	Hydraulic Geometry at Trail and International Boundary Gauging Stations, Table 7, page 16, Opinion on the Transport of Metallurgical Slag by the Columbia River,
			Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
259	1440	McLean	Surface Grain Size Statistics, Table 8, page 18, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest
			Hydraulic Consultants, September 17, 2010
260	1440	McLean	Sub-surface Grain Size Statistics, Table 9, page 21, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary,
			Northwest Hydraulic Consultants, September 17, 2010
261	1440	McLean	Sediment Transport Characteristics of Slag Particles, Table 10, page 28, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to
			International Boundary, Northwest Hydraulic Consultants, September 17, 2010
262	1440	McLean	Critical Velocity for Initiation of Slag Transport and Suspension, Table 11, page 29, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to
			International Boundary, Northwest Hydraulic Consultants, September 17, 2010
263	1440	McLean	Comparison of Reach-average Hydraulic Properties from Trail, BC to International Boundary and International Boundary to Northport, Washington, Table 12, page
			39, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
264	1440	McLean	Summary of Sediment Samples Collected in April 2010 and the Subsequent Analysis that was Completed, Table 13, page 51, Opinion on the Transport of
			Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
265	1440	McLean	TAL Analysis Results from April 2010 Samples, Table 14, page 63, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International
			Boundary, Northwest Hydraulic Consultants, September 17, 2010
266	1440	McLean	Percent of Sediment that was Physically Identified as Slag, Table 15, page 66, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to
			International Boundary, Northwest Hydraulic Consultants, September 17, 2010
267	1440	McLean	Distinct Identifiable Sedimentary Units and Their Slag Content, Table 16, page 69, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to
			International Boundary, Northwest Hydraulic Consultants, September 17, 2010
268	1440	McLean	Net Volume Changes Over Time at Fort Shepherd and Waneta Pools, Table 17, page 74, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail
			B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
269	1440	McLean	Sediment and Slag Deposition Volumes for Different Sedimentary Units, Table 18, page 75, Opinion on the Transport of Metallurgical Slag by the Columbia River,
			Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
270	1440	McLean	Study Area, Figure 1, page 6, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic
			Consultants, September 17, 2010
271	1440	McLean	Columbia River and Tributaries Upstream, Figure 2, page 11, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International
			Boundary, Northwest Hydraulic Consultants, September 17, 2010
272	1440	McLean	Columbia River Hydrograph at International Boundary Before and After Flow Regulation, Figure 3, page 15, Opinion on the Transport of Metallurgical Slag by the
			Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
273	1440	McLean	Variation in Peak and Mean Annual Discharges Based on the WSC Hydrometric Gauge Records, Figure 4, page 15, Opinion on the Transport of Metallurgical Slag by
			the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
274	1440	McLean	HydraulicGeometry Measurements at Trail and International Boundary Hydrometric Stations, Figure 5, page 17, Opinion on the Transport of Metallurgical Slag by
			the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
275	1440	McLean	Surface Sampling Sites, Figure 6, page 19, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest
			Hydraulic Consultants, September 17, 2010
276	1440	McLean	Surface Grain Size Distribution of River Bed Sediments, Figure 7, page 20, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to
			International Boundary, Northwest Hydraulic Consultants, September 17, 2010
277	1440	McLean	Sub-surface Grain Size Distribution of River Bed Sediments, Figure 8, page 20, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to
			International Boundary, Northwest Hydraulic Consultants, September 17, 2010
278	1440	McLean	Estimated Annual Slag Production at Teck Cominco Smelter in Trail, Figure 9, page 23, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C.
	1		to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
279	1440	McLean	Slag Discharge Site at Trail in 1992, Figure 10, page 24, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary,
			Northwest Hydraulic Consultants, September 17, 2010

Trial Exhibit No.	Dep. Exhibit No.	Deponent	Title
280	1440	McLean	Grain Size Distribution of Grab Samples, (SL 1 through SL4) Collected from the River Bed Below Teck Cominco, Figure 11, page 26, Opinion on the Transport of
200	1		Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
281	1440	McLean	Shields' Incipient Motion Relation for Granular Sediment Subject to River Currents, Figure 12, page 27, Opinion on the Transport of Metallurgical Slag by the
			Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
282	1440	McLean	Transport and Suspension of Slag Particles in Columbia River at Trail and International Boundary Hydrometric Station Sites in 1953 and 1993, Figure 13, page 31,
			Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
283	1440	McLean	Portion of Canadian Hydrographic Service Chart 3055 of Columbia River, Figure 14, page 33, Opinion on the Transport of Metallurgical Slag by the Columbia River,
204	1110	NA-L	Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
284	1440	McLean	Cross Section Locations, Figure 15, page 34, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest
205	1110	1.4-L	Hydraulic Consultants, September 17, 2010
285	1440	McLean	Computed Water Surface Profiles Along Columbia River from Northport, Washington to Birchbank, BC, Figure 16, page 35, Opinion on the Transport of Metallurgical
286	1110	1.4-L	Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
286	1440	McLean	Variation in Mean Channel Velocity from Northport Washington to Birchbank, BC, Figure 17, page 37, Opinion on the Transport of Metallurgical Slag by the Columbia
287	1440	McLean	River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010 Variation in Bed Shear Stress from Northport, Washington to Birchbank, BC, Figure 18, page 38, Opinion on the Transport of Metallurgical Slag by the Columbia
287	1440	McLean	
288	1440	McLean	River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010 SRH-1D Simulation 1: One-Year Simulation of Slag Transport for the Hypothetical Starting Situation of a 1 m Thick Slag Deposit on River Bed Between Trail and the
200	1440	Micheall	International Boundary, Figure 19, page 41, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest
289	1440	McLean	Hydraulic Consultants. September 17. 2010 SRH-1D Simulation 2: Five-Year Simulation of Slag Transport for the Hypothetical Starting Situation of a 1 m Thick Slag Deposit on River Bed Between Trail and the
203	1440	Wickean	International Boundary, Figure 20, page 43, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest
			Hydraulic Consultants. September 17, 2010
290	1440	McLean	Example of Flow Field at the Confluence of the Columbia River and Pend d'Oreille River, Figure 21, page 45, Opinion on the Transport of Metallurgical Slag by the
230	1440	Wickean	Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
291	1440	McLean	Location of Each Sampling Site and Key Geographic Features, Figure 22, page 47, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to
231	1440	Wiczcan	International Boundary. Northwest Hydraulic Consultants. September 17, 2010
292	1440	McLean	Concentrations of Metals Associated with Slag Along the Columbia River, Figure 23, page 62, Opinion on the Transport of Metallurgical Slag by the Columbia River,
			Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
293	1440	McLean	Metal Concentrations Associated with the SL4 Sample for Five Grain Sizes Classes and a Composite Sample, Figure 24, page 64, Opinion on the Transport of
			Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
294	1440	McLean	Scour and Fill at Ft. Shepherd Pool and Waneta Pool, 1948 to 1989, Figure 25, page 71, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail
			B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
295	1440	McLean	Scour and Fill at Ft. Shepherd Pool and Waneta Pool, 1989 to 2010, Figure 26, page 72, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail
			B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
296	1440	McLean	Subsurface Sediment Below Armour at Site B3, Photo 1, page 48, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International
			Boundary, Northwest Hydraulic Consultants, September 17, 2010
297	1440	McLean	Bagged Samples (250 g) for TAL, Photo 2, page 49, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary,
			Northwest Hydraulic Consultants, September 17, 2010
298	1440	McLean	Ekman Dredge Used to Collect Samples from Bottom of River in Pools, Photo 3, page 50, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail
			B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
299	1440	McLean	Location of Grab Samples (SL1-4) at Trail BC, Photo 4, page 52, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International
			Boundary, Northwest Hydraulic Consultants, September 17, 2010
300	1440	McLean	Sampling Sites A1 through A6, Photo 5, page 53, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary,
			Northwest Hydraulic Consultants, September 17, 2010
301	1440	McLean	Site B4 Where a Bulk Sample and 60 cm Deep Profile in the Bar was Dug, Photo 6, page 54, Opinion on the Transport of Metallurgical Slag by the Columbia River,
			Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
302	1440	McLean	Site B2 Where a Bulk Sample and 100 cm Deep Profile in the Bar was Dug, Photo 7, page 55, Opinion on the Transport of Metallurgical Slag by the Columbia River,
			Trail B.C. to International Boundary, Northwest Hydraulic Consultants, September 17, 2010
303	1440	McLean	Sample Sites B3, B5 and B6, Photo 8, page 56, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest
			Hydraulic Consultants, September 17, 2010

Trial	Dep.		
	Exhibit No.	Deponent	Title
304	1440	McLean	Sample Sites B7, B8 and B9, Photo 9, page 57, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest
304	1440	WICECUIT	Hydraulic Consultants. September 17, 2010
305	1440	McLean	Declaration and Resume of Dr. David G. McLean, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary,
	1	111020011	Northwest Hydraulic Consultants, September 17, 2010, Appendix A
306	1440	McLean	HEC/RAS Model of Columbia River, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic
			Consultants, September 17, 2010, Appendix B
307	1440	McLean	Sediment Sampling Plan, Opinion on the Transport of Metallurgical Slag by the Columbia River, Trail B.C. to International Boundary, Northwest Hydraulic
			Consultants, September 17, 2010, Appendix C
308	1441	McLean	Reference Distances, Table 1, page 4, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants,
			May 13, 2011
309	1441	McLean	Rapids on Upper Columbia River Before Grand Coulee Dam, Table 2, page 11, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia
			River, Northwest Hydraulic Consultants, May 13, 2011
310	1441	McLean	Summary of historical suspended sediment data - Columbia River at Birchbank, Table 3, page 15, Opinion on the Transport and Fate of Metallurgical Slag Discharged
			into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
311	1441	McLean	Variation in settling velocity and settling time with particle size for a reservoir 50 ft. deep, Table 4, page 32, Opinion on the Transport and Fate of Metallurgical Slag
			Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
312	1441	McLean	Comparison of predicted and measured sediment transport from Yang (1996), Table 5, page 37, Opinion on the Transport and Fate of Metallurgical Slag Discharged
			into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
313	1441	McLean	Summary of discharge and water level 22-29 March 2011), Table 6, page 60, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia
			River, Northwest Hydraulic Consultants, May 13, 2011
314	1441	McLean	Study area showing Trail and LeRoi smelters, Figure 1, page 5, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River,
			Northwest Hydraulic Consultants, May 13, 2011
315	1441	McLean	Study area showing dams in the Upper Columbia River watershed, Figure 2, page 6, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the
			Columbia River, Northwest Hydraulic Consultants, May 13, 2011
316	1441	McLean	Study area showing mine locations, Figure 3, page 7, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest
			Hydraulic Consultants, May 13, 2011
317	1441	McLean	Location map showing selected stream flow gages, Figure 4, page 8, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River,
			Northwest Hydraulic Consultants, May 13, 2011
318	1441	McLean	Time line for the Upper Columbia River, Figure 5, page 9, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest
			Hydraulic Consultants, May 13, 2011
319	1441	McLean	Monthly flow hydrograph and reservoir level, showing the difference between pre-regulation (1965) conditions and post-regulation (1984) conditions, Figure 6, page
			10, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
320	1441	McLean	Profile of Upper Columbia River from Grand Coulee Dam to International Boundary, Figure 7, page 12, Opinion on the Transport and Fate of Metallurgical Slag
			Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
321	1441	McLean	Aerial photos of the Little Dalles before and after channel modifications, Figure 8, page 14, Opinion on the Transport and Fate of Metallurgical Slag Discharged into
			the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
322	1441	McLean	Suspended sediment rating curves at Northport and Birchbank (Trail), Figure 9, page 16, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the
			Columbia River, Northwest Hydraulic Consultants, May 13, 2011
323	1441	McLean	Distribution of sediment sizes along reservoir, Figure 10, page 17, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River,
			Northwest Hydraulic Consultants, May 13, 2011
324	1441	McLean	Distribution of sediment sizes along reservoir, Figure 11, page 18, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River,
			Northwest Hydraulic Consultants, May 13, 2011
325	1441	McLean	Location of Midnite Mine, Figure 12, page 28, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic
			Consultants, May 13, 2011
326	1441	McLean	USGS hydraulic measurements that were ignored in Brown's analysis of Midnite Mine, Figure 13, page 30, Opinion on the Transport and Fate of Metallurgical Slag
			Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
327	1441	McLean	Sediment deposition and delta formation on Midnite Mine tributary creek indicating sediment transport is reducing along the stream, Figure 14, page 31, Opinion on
			the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
328	1441	McLean	Eddy formation off a natural bedrock spur creating sediment deposition at Black Sand Beach, Figure 15, page 41, Opinion on the Transport and Fate of Metallurgical
			Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011

Trial	Dep.		
Exhibit No.	Exhibit No.	Deponent	Title
329	1441	McLean	Comparison of 1D and 2D representation of flow in China Bend, Figure 16, page 42, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the
329	1441	ivictean	
330	1441	McLean	Columbia River, Northwest Hydraulic Consultants, May 13, 2011 Eddy near Flat Creek in China Bend, Upper Columbia River, Figure 17, page 43, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia
330	1441	IVICLEATI	
331	1441	McLean	River, Northwest Hydraulic Consultants, May 13, 2011 Regional sediment yield data used to estimate tributary sediment inflows, Figure 18, page 47, Opinion on the Transport and Fate of Metallurgical Slag Discharged
331	1441	IVICLEATI	into the Columbia River. Northwest Hydraulic Consultants. May 13, 2011
332	1441	McLean	Location of dam sites used for determining tributary sediment loads, Figure 19, page 49, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the
332	1441	Wicecan	Columbia River. Northwest Hydraulic Consultants. May 13. 2011
333	1441	McLean	Comparison of recent Columbia River bathymetric surveys, Figure 20, page 53, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia
333	1441	Wiczcuii	River. Northwest Hydraulic Consultants. May 13. 2011
334	1441	McLean	HEC-RAS output screen from Bradley's Natural Sediment model, Figure 21, page 55, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the
			Columbia River. Northwest Hydraulic Consultants. May 13. 2011
335	1441	McLean	Computed bed and water surface profiles at the beginning (1898) and end (2009) of the "Natural Sediment" HEC-RAS model, Figure 22, page 56, Opinion on the
			Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
336	1441	McLean	Change of bed elevation over time at RS 727.3334 and 727.3438 computed by Bradley's "Natural Sediment", "Teck Slag", and "LeRoi" (1898; 1916) models, Figure
			23, page 57, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
337	1441	McLean	Comparison on HEC-RAS cross-sections at the Little Dalles based on 1949 USCGS bathymetric data and bathymetric data obtained in March 2011, Figure 24, page 59,
			Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
338	1441	McLean	Comparison of Cross-section bed profiles and observed water surface elevation downstream of the Little Dalles at RS 727.3334, Figure 25, page 61, Opinion on the
			Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
339	1441	McLean	Downstream facing photographs fo the Little Dalles reach taken during site visit on March 26, 2011, Figure 26, page 62, Opinion on the Transport and Fate of
			Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
340	1441	McLean	Computed bed and water surface profiles, and observed conditions from March 22-29, 2011 from RM 730 to 762, Figure 27, page 64, Opinion on the Transport and
			Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
341	1441	McLean	Comparison of HEC-RAS cross-sections at Waneta Eddy based on 1949 USCGS bathymetric data and 1989 WSC bathymetric data, Figure 28, page 66, Opinion on the
			Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
342	1441	McLean	Photograph of the confluence of the Pend Oreille and Columbia Rivers at the Waneta Eddy showing absence of waterfall, Figure 29, page 67, Opinion on the
			Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
343	1441	McLean	USACE 1898 chart, 1930 aerial photo, and computed water surface profile at the downstream end of Elbow Bend, Figure 30, page 69, Opinion on the Transport and
			Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
344	1441	McLean	USACE 1898 chart, 1930 aerial photo, and computed water surface profkle midstream at Elbow Bend, Figure 31, page 70, Opinion on the Transport and Fate of
2.45	1111		Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
345	1441	McLean	USACE 1898 chart, 1930 aerial photo, and computed water surface profile at the upstream end of Elbow Bend, Figure 32, page 71, Opinion on the Transport and Fate
346	1441	Malaan	of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011 Residence time and slag particles computed by 3D model at China Bend, Figure 34, page 75, Opinion on the Transport and Fate of Metallurgical Slag Discharged into
346	1441	McLean	
347	1441	McLean	the Columbia River, Northwest Hydraulic Consultants, May 13, 2011 Elbow Rapid, River Mile 600, Photo 1, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants,
347	1441	IVICLEAII	May 13, 2011
348	1441	McLean	Turtle Rapid, River Mile 605, Photo 2, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants,
340	1441	Wickean	May 13. 2011
349	1441	McLean	Grand Rapids, River Mile 650, Photo 3, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic
343	1441	Wickean	Consultants, May 13, 2011
350	1441	McLean	Kettle Falls, River Mile 670, Photo 4, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants,
			May 13. 2011
351	1441	McLean	Little Dalles, River Mile 728, Photo 5, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants,
-		×===	May 13. 2011
352	1441	McLean	Murphy's Rapid, River Mile 743, Photo 6, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic
			Consultants, May 13, 2011
353	1441	McLean	Response to Comments on McLean (2010) Report, Appendix A, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River,
			Northwest Hydraulic Consultants, May 13, 2011

Trial	Dep.		
Exhibit No.	Exhibit No.	Deponent	Title
354	1441	McLean	Columbia River, Panel 1, Monaghan Rapid, Rattlesnake Rapid, Pen-Waw Bar, Coulee Bend, Appendix B, Opinion on the Transport and Fate of Metallurgical Slag
			Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
355	1441	McLean	Columbia River, Panel 2, Hell Gate, Spokane Rapid, China Camp Rapid, Appendix B, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the
			Columbia River, Northwest Hydraulic Consultants, May 13, 2011
356	1441	McLean	Columbia River, Panel 3, Turtle Rapid, Landslide Rapid, Elbow Bend, Appendix B, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the
			Columbia River, Northwest Hydraulic Consultants, May 13, 2011
357	1441	McLean	Columbia River, Panel 4, Grand Rapids, Gifford's Rapids, Appendix B, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River,
			Northwest Hydraulic Consultants, May 13, 2011
358	1441	McLean	Columbia River, Panel 5, Nine Mile Rapids, Kettle Falls, Appendix B, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River,
			Northwest Hydraulic Consultants, May 13, 2011
359	1441	McLean	Columbia River, Panel 6, Sheep Creek Bend, Two Mile Rapid, Little Dalles, Deadman's Eddy, Bishop's Bar, Appendix B, Opinion on the Transport and Fate of
			Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
360	1441	McLean	Gravel Bar Site Inspections, Figure C.1, Appendix C, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic
			Consultants, May 13, 2011
361	1441	McLean	Sheep Creek Site, (a) vicinity map and location of sediment survey, (b) photo of gravel bar and river, (c) surface armor layer at exposure, (d) subsurface material at
			exposure, (e) slag particles, Figure C.2, Appendix C, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic
			Consultants, May 13, 2011
362	1441	McLean	Bishop's Bar Site, (a) vicinity map and location of sediment survey, (b) photo of gravel bar and river, (c) surface armor layer at exposure, (d) slag particles, (e)
			subsurface material at exposure in sand deposit in lea of gravel bar, Figure C.3, Appendix C, Opinion on the Transport and Fate of Metallurgical Slag Discharged into
			the Columbia River. Northwest Hydraulic Consultants. May 13. 2011
363	1441	McLean	China Bend Site, (a) vicinity map and location of sediment survey, (b) photo of bar and river, (c) surface armor layer (with mud) at exposure, (d) slag particles, (e)
			subsurface material at exposure, Figure C.4, Appendix C, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest
			Hydraulic Consultants. May 13, 2011
364	1441	McLean	Twelve Mile Bar (a) vicinity map and location of sediment survey, (b) photo of bar and river, (c) surface armor layer (with mud) at exposure, (d) subsurface material
			at exposure, (e) slag particles, Figure C.5, Appendix C, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest
			Hydraulic Consultants. May 13, 2011
365	1441	McLean	Marcus Flats Site, (a) vicinity map and location of sediment survey, (b) photo of Marcus Flats (c) armor layer at exposure near river's edge, (d) exposure in mudflat,
			(e) slag particle collected from main channel adhering to magnet, Figure C.6, Appendix C, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the
			Columbia River. Northwest Hydraulic Consultants. May 13. 2011
366	1441	McLean	Acoustic Doppler Current Profiler (ADCP) Transect Survey, Dead Man's Eddy and China Bend Reaches, Upper Columbia River, Northport, WA, March 2011, Appendix
			C, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
367	1441	McLean	Modeling Flow and Sediment Transport in the Upper Columbia River, Appendix D, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the
			Columbia River, Northwest Hydraulic Consultants, May 13, 2011
368	1441	McLean	Two/dimensional Hydraulic Modeling of Selected Reaches in the Upper Columbia River, Appendix E, Opinion on the Transport and Fate of Metallurgical Slag
			Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
369	1441	McLean	Appendix F, Opinion on the Transport and Fate of Metallurgical Slag Discharged into the Columbia River, Northwest Hydraulic Consultants, May 13, 2011
370			Duplicate Exhibit
371			Duplicate Exhibit
372	1506	Medine	Location map for the mines, mills, and smelters addressed in Teck's reports, Figure 1-1, page 5, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
373	1506	Medine	The Upper Columbia River (UCR) from the Grand Coulee Dam to the border with Canada, downstream of the Teck Smelter (CH2MHill, 2006, Figure 1-3, page 6,
			Expert Rebuttal Report of Allen J. Medine, May 13, 2011
374	1506	Medine	Brown's ore production vs. waste rock generation, Figure 4-2, page 32, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
375	1506	Medine	The data used by Brown to represent the average waste rock composition for lead and zinc, Figure 4-3, page 36, Expert Rebuttal Report of Allen J. Medine, May 13,
			2011
376	1506	Medine	The total mass of waste rock contributed by differing mine types in Brown's analysis of waste rock, Figure 4-4, page 36, Expert Rebuttal Report of Allen J. Medine,
			May 13, 2011
377	1506	Medine	Midnite Mine located near Blue Creek in the Spokane River drainage basin. The mine site is approximately 4-5 miles from the Spokane River, Figure 4-5, page 3,
	-555	came	Expert Rebuttal Report of Allen J. Medine, May 13, 2011
378	1506	Medine	South Spoils (Gully waste Rock) at the Midnite Mine Site looking over the vegetated area toward the East Drainage. Pollution control pond in the lower right portion
3,0		ivicume	of the photo (Medine photo), Figure 4-6, page 37, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
379	1506	Medine	Brown's "Relationship" Between Waste Rock and Pile Surface Area, Figure 4-7, page 42, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
3,3	-500	iticuliic	5.5. Academican Services Waste Note and the Sanace Med, 18are 4 7, page 42, Expert nebattal neport of Anches Medalic, May 13, 2011

Trial Exhibit No.	Dep. Exhibit No.	Deponent	Title
380	1506	Medine	Copper Ore Data for the Greenwood Smelter and "Boundary District", Figure 5-1, page 50, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
381	1506	Medine	Sample location map for the Northport-Le Roi smelter area showing the river sample location, Figure 5-2, page 52, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
382	1506	Medine	Mass Balance Analysis of Pend Oreille Mill for 1957-1958 Showing Tonnages of Ore, Concentrates, and Tailings and the Lead and Zinc Content, Table 3-1, page 14, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
383	1506	Medine	The Comparison of Calculated Values for Tailings and Measured Values and the Effects of Small Changes in the % Metal Content on Tonnage Comparisons, Table 3-2, page 15. Expert Rebuttal Report of Allen J. Medine, May 13, 2011
384	1506	Medine	Comparison of Data from Kinney's Report and Rex Bull's Calculated Metals in Tailings, Table 3-3, page 16, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
385	1506	Medine	Verification of Bull's Spreadsheet Input Values From PIMRs For Each Mill, Table 3-4, page 20, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
386	1506	Medine	Errors in the Metal Content of Tailings as Calculated by Bull, Table 3-5, page 22, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
387	1506	Medine	Summary of Constituents from Page iv and Table 4 on Page 10 of Brown's Expert Report, Table 4-1, page 24, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
388	1506	Medine	Summary of the Amounts of Tailing Generated at the Mills and the Tailing Remaining On-Site, Table 4-2, page 26-27, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
389	1506	Medine	Tailings Sampled used for the Pend Oreille, Josephine and Grandview-Metaline Mines/Mills, Table 4-3, page 30, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
390	1506	Medine	Metal Concentrations in Waste Rock from the Midnite Mine, Table 4-4, page 39, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
391	1506	Medine	Summary of McNulty's approach for Northport Smelter and Application to Other Smelters, Table 5-1, page 44, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
392	1506	Medine	Resume of Allen J. Medine, Appendix A, page 53, Expert Rebuttal Report of Allen J. Medine, May 13, 2011
393	267	Nener	Letter from Lisa Riddle/CA Dept of Justice to McNevin re terms of Nener's deposition
394	270	Nener	Columbia River Integrated Environmental Monitoring Program (CRIEMP) 1991 - 1993 Interpretive Report, by Aquametrix Research Ltd.
395	1415	Nener	DRAFT Cominco Slag Survival and Water Quality Results of Bioassays on Five Species of Aquatic Organisms, by Nener
396	NA	Passmore	Invoices and contract from Fulcrum Environmental Consulting
397	NA	Passmore	Detail of payments to Fulcrum Environmental Consulting
398			Deleted Exhibit
399			Deleted Exhibit
400			Deleted Exhibit
401	NA	Passmore	Records of expense reimbursement for RI/FS related travel
402	NA	Passmore	Compensation records for Don Hurst
403	NA	Passmore	Time records for Don Hurst
404	NA	Passmore	Compensation records for Gary Passmore
405	NA	Passmore	Time records for Gary Passmore
406	NA	Passmore	Compensation records for Patti Bailey
407	NA	Passmore	Time records for for Patti Bailey
408	1226	Paulson	Elemental Concentrations of Sediment and Liquids in Contact with Lk Roosevelt Sediments
409	1230	Paulson	Elemental Concentrations of Sediment and Liquids in Contact with Sediments within Lake Roosevelt in September 2004
410	1231	Paulson	Presentation to Lake Roosevelt Water Quality Council: The Effects of Trace Elements on Water Quality and Biological Helath in the Lake Roosevelt National Recreational Area
411	1234	Paulson	Presentation to the Lake Roosevelt Water Quality Council: The Effects of Trace Elements on Water Quality and Biological Health in the Lake Roosevelt National Recreational Area: Columbia River in Cooperation with NPS dup??
412	1235	Paulson	Concentrations of Elements in Sediments and Selective Fractions of Sediments, and in Natural Waters in Contact with Sediments from Lake Roosevelt, September 2004
413	1236	Paulson	Presentation to Lake Roosevelt Water Quality Council: Release of elements from sediments to waters of Lake Roosevelt
414	1495	Queneau	Photo, Trail Creek in 1896, Trail Historical Society, photo no. 1829 (Figure 1, page 19, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
415	1495	Queneau	Photo, View of the Trail Copper Smelter in 1896, B.C. Archives (Figure 2, page 25, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
416	NA	Queneau	Photo, 1900, Trail Historical Society (Canadian Smelting Works, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
417	NA	Queneau	Photo, 1904, Trail Historical Society (Trail and Smelter, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)

Trial Exhibit No.	Dep. Exhibit No.	Deponent	Title
418	NA	Queneau	Photo, 1907 Smelter and Bay Avenue Bridge, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 13, 2011
419	NA	Queneau	Photo, 1910, Slag filling in Bay Avenue, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 13, 2011
420	NA	Queneau	Photo, 1910 (JFH Expert Report on page 13, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
421	NA	Queneau	Photo, 1927, Trail Historical Society (Trail Smelter, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
422	NA	Queneau	Photo, 1927, Trail Historical Society (Trail Smelter, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
423	NA	Queneau	Photo, 1930, Trail Historical Society(Trail Smelter and Pine Avenue, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
424	NA	Queneau	Photo, No date, Trail Historical Society (Slag Launders from Different Angle, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
425	NA	Queneau	Photo, 2010, Google Earth (Slag Dump Area, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
426	NA	Queneau	Photo, 2010, Google Earth (Slag Dump Area Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
427	NA	Queneau	Map, 1910 (City of Trail, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011)
428	NA	Queneau	Photo, 1910 CM&S Smelter about 1910 – Slag pile at left was used to fill inTrail Creek gully, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
429	NA	Queneau	Photo, 1924, Bay and Cedar Avenue from Smelter, Appendix J, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
430			Deleted Exhibit
431	1495	Queneau	View of Trail's BF Slag Fuming Plant Under Construction in about 1930, Figure 3, page 25, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
432	1495	Queneau	Interior View of the Early Betts Electrolytic Refinery Showing the Arrangement of the Cells, Figure 4, page 27, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
433	1495	Queneau	Hand Sorting to Separate Lead and Zinc Minerals at the Sullivan Mine, Figure 5, page 29, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
434	1495	Queneau	Early Wooden Flotation Cells Used to Produce Separate Lead and Zinc Sulfide Concentrates, Figure 6, page 29, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
435	1495	Queneau	The Secret Heavy Water Plant at Trail, One of Cominco's Many War-Time Contributions, Figure 7, page 32, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
436	1495	Queneau	Water-jacketed Blast Furnace, Figure 8, page 53, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
437	1495	Queneau	Blast Furnace, a Section View, Figure 9, page 54, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
438	1495	Queneau	Tapping a Reverberatory Furnace, Figure 10, page 56, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
439	1495	Queneau	Herreshoff Multiple-Hearth Roaster, Figure 11, page 58, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
440	1495	Queneau	Dwight & Lloyd Continuous Sintering Machine, Figure 12, page 59, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
441	1495	Queneau	Early Copper Converters at Use in the Trail Smelter, Figure 13, page 62, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
442	1495	Queneau	Lead Smelter Flow, Figure 14, page 65, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
443	1495	Queneau	Charging a Lead-BF Slag Fuming Furnace at Trail, Figure 15, page 72, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
444	1495	Queneau	Trail's Water-jacketed Fuming Furnace with 35 Tuyeres, Figure 16, page 72, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
445	1495	Queneau	A Suspension Multiple-Hearth Roaster with Boiler, Cyclone Dust Collector, Balloon Flue, Cottrell and Acid Plant, Figure 17, page 74, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
446	1495	Queneau	A Simplified Trail Zinc-Processing Diagram, Including Fertilizer Operations, Figure 18, page 76, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
447	1495	Queneau	Simplified History of Trail's Lead-Zinc Smelting Processes, Figure 19, page 78, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
448	1495	Queneau	Simplified Flow Diagram of the Sulphur Dioxide Recovery, the Sulphuric Adic, the Ammonium Sulhate and the ZnMnS Processes, Figure 20, page 84, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
449	1495	Queneau	Simplified Flow Diagram of the Lead Sintering Process, Figure 21, page 86, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
450	1495	Queneau	Construction of the Effluent-Treatment-Plant Thickener to Collect Heavy-Metal Precipitate from Waste Water, Figure 22, page 106, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
451	1495	Queneau	Trail's Kivcet Furnace, Figure 23, page 115, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
452	1495	Queneau	Discharge of Effluents from Trail Metallurgical Sewers into the Columbia River in 1927, Figure 24, page 118, Expert Opinion and Rebuttal of Paul B. Queneau, May 12 2011
453	1495	Queneau	Cominco Metals Slag Discharge from Sewer #1 on the West Bank of the Columbia River Just Upstream from the Highway 3 Bridge, Figure 25, page 119, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
454	1495	Queneau	Fumed Slag Particle Size Distribution and Analyses at Start, Middle and End of Tapping, Figure 26, page 123, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
4EE	1.40E	Oueneau	Marrian Outfalls Sigure 27, page 127, Expert Opinion and Robuttal of Paul B. Outgroom May 12, 2011

Mercury Outfalls, Figure 27, page 127, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011

455

1495

Queneau

Trial	Dep.		
Exhibit No.	Exhibit No.	Deponent	Title
456	1495	Queneau	Average Daily Measurements of Total and Dissolved Metals (Pb, Zn, Cd, As, Cu and Hg) for Various Periods Between 1980 and 1996, Figure 28, page 130, Expert
			Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
457	1495	Queneau	The Silver Refinery, Figure A1, page 142, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
458	1495	Queneau	The Antimonial Lead Plant, Figure A2, page 144, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
459	1495	Queneau	Typical Trail Feed Concentrate Analyses, Table 1, page 28, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
460	1495	Queneau	Summary of Non-Slag Discharges, Primarily to the Columbia River, Table 2, page 131, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
461	1495	Queneau	Summary of Metal Discharges in Slag to the Columbia River, Table 3, page 131, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
462	1495	Queneau	Sinter-Plant Feedstocks, Table A1, page 139, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
463	1495	Queneau	Representative Analyses of Metallurgical Products, Table A2, page 140, Expert Opinion and Rebuttal of Paul B. Queneau, May 13, 2011
464	1495	Queneau	Typical Analyses of Silver Refinery Products, Table A3, page 143, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
465	1495	Queneau	Average Analyses of Materials from the Antimonial Lead Plant, Table A4, page 144, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
466	1495	Queneau	Fume Plant Feed and Leach Residue, Table A5, page 146, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
467	NA	Queneau	Explanation of Spreadsheet Details, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
468	NA	Queneau	Spreadsheet 6, Slag Discharge, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
469	NA	Queneau	Spreadsheet 8, Non-Slag Discharge, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
470	NA	Queneau	Spreadsheet 19, Calculation of Slag Volume, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
471	1495	Queneau	Paul B. Queneau C.V., page 152, Appendix E, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011,
472	1495	Queneau	Response to John F. Higginson's Additional Comments Identifying Errors in Mr. Queneau's Historical Review, Appendix F, page 161, Expert Opinion and Rebuttal of
772	1433	Queneau	Paul B. Queneau, May 12, 2011
473	1495	Queneau	Response to John F. Higginson's Critique of the "Inputs and Distributions Spreadsheets", Appendix G, page 165, Expert Opinion and Rebuttal of Paul B. Queneau,
			May 12. 2011
474	1495	Queneau	Response to John F. Higginson's Critique of the "Explanation of Spreadsheet Details", Appendix H, page 170, Expert Opinion and Rebuttal of Paul B. Queneau, May
			13, 2011
475	1495	Queneau	Response to JFH's Opinion #2 – Constant Properties of Barren slag put into Columbia River, Appendix I, page 171, Expert Opinion and Rebuttal of Paul B. Queneau,
			May 12, 2011
476	257	Queneau	Slag Production Estimates From Pb Production Data (From Annual Reports), Calculated Slag to River and Measured Slag to River, (Calculated from Metallurgical
477	257	0	Balance), Table 1, Appendix K, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
477	257	Queneau	Comparison of Slag Calculated Based on Pb Produced as Compared to Slag Determined by Metallurgical Balance, Table 2, Appendix K, Expert Opinion and Rebuttal of
478	257	Queneau	Paul B. Queneau, May 12, 2011 Metal Loads via Slag per Year to the River Based on Metallurgical Balance Data and Slag Composition by Percentage, Table 3, Appendix K, Expert Opinion and
478	257	Queneau	Rebuttal of Paul B. Queneau, May 12, 2011
479	257	Queneau	Estimate of Metals to River via Slag Discharge, Table 4, Appendix K, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
480	1495	Queneau	Tabulation of Recorded Spills, Appendix L, page 176, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
481			Deleted Exhibit
482			Deleted Exhibit
483			Duplicate Exhibit
484			Duplicate Exhibit
485	1		Duplicate Exhibit Duplicate Exhibit
486			Duplicate Exhibit Duplicate Exhibit
487			Duplicate Exhibit Duplicate Exhibit
			· ·
488 489			Duplicate Exhibit Duplicate Exhibit
-	 		
490			Duplicate Exhibit Duplicate Exhibit
491			Duplicate Exhibit
492			Duplicate Exhibit
493			Duplicate Exhibit
494			Duplicate Exhibit
495			Deleted Exhibit

Trial	Don		
1	Dep. Exhibit No.	Deponent	Title
496	EXHIBIT NO.	Deponent	Duplicate Exhibit
497	1		Duplicate Exhibit Duplicate Exhibit
498	+		Duplicate Exhibit Duplicate Exhibit
499			Duplicate Exhibit Duplicate Exhibit
500			Duplicate Exhibit Duplicate Exhibit
	-		'
501 502			Duplicate Exhibit Duplicate Exhibit
			Duplicate Exhibit
503			Duplicate Exhibit
504			Duplicate Exhibit
505	1		Duplicate Exhibit
506			Duplicate Exhibit
507	NA	Queneau	Spreadsheet 10, Emissions of Metals to Atmosphere, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
508	NA	Queneau	Spreadsheet 11, Metal Outfalls, Primarily to the Columbia River, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
509	NA	Queneau	Spreadsheet 12, Arsenic Balance, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
510	NA	Queneau	Spreadsheet 13, Cadmium Balance, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
511	NA	Queneau	Spreadsheet 14, Lead Balance, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
512	NA	Queneau	Spreadsheet 15, Mercury Balabce, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
513	NA	Queneau	Spreadsheet 16, Zinc Balance, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
514	NA	Queneau	Spreadsheet 18, Fertilizer Balance, Appendix D, Expert Opinion and Rebuttal of Paul B. Queneau, May 12, 2011
515	NA	Queneau	D.D. Logan, Memo to the BC Ministry of Environment
516			Deleted Exhibit
517	NA	Queneau	Anonymous, Memo and Tables re: Slag Released to the Columbia River and Percentage Composition of Metals
518	NA	Roland	Remedial Site Assessment Decision EPA Region X, Dec. 2000
519			Duplicate Exhibit
520			Duplicate Exhibit
521	NA	Roland/Tonel	EPA's Phase I Sediment Sampling Data Evaluation Report, August 25, 2006
522	NA	Roland/Tonel	Modified RI/FS Workplan for the Upper Columbia River, Volume I
523	NA	Roland/Tonel	Modified RI/FS Workplan for the Upper Columbia River, Volume II
524	NA	Roland	Hopkins, B.S., D.K. Clark, M. Schlender, and M. Stinson. 1985. Basic Water Monitoring Program: Fish tissue and sediment sampling for 1984. Pub. No. 85-7,
			Washington State Department of Ecology, Olympia, WA
525	1069	Roland	Johnson, A., D. Norton, and B. Yake. 1988. An assessment of metals contamination in Lake Roosevelt; revised 1989. Pub. No. 89-e26. Washington State Department
526	1070		of Ecology, Olympia, WA
526	1072	Roland	Johnson, A., 1991. Review of Metals, Bioassay, and Macroinvertebrate Data from Lake Roosevelt Benthic Samples Collected in 1989. Pub. No. 91-e23.
527	1073	Roland	Memorandum to Carl Nuechterlein, Washington State Department of Ecology, Olympia, WA Serdar, D., A. Johnson, and K. Seiders. 1993. Interim report on monitoring contaminant trends in Lake Roosevelt. Pub. No. 93-e53. Washington State Department of
327	1073	Notatiu	Ecology, Olympia, WA
528	1074	Roland	Serdar, D., B. Yake, and J. Cubbage. 1993. Contaminant trends in Lake Roosevelt. Pub. No. 94-185. Washington State Department of Ecology, Olympia, WA
529	1075	Roland	Era, B. and D. Serdar. 2001. Reassessment of toxicity of Lake Roosevelt sediments. Pub. No. 01-03-043. Washington State Department of Ecology, Olympia, WA
323	1075	11010110	
530	NA	Roland	Recommendations for Further Evaluations of Sediment Chemistry and Sediment Toxicity in the Upper Columbia River Submitted to Department of Ecology by Don
			MacDonald, MacDonald Environmental Sciences Ltd., June 30, 2011
531	1152	Roland	FIELD RECONNAISSANCE AND SEDIMENT SAMPLING REPORT, Upper Columbia River Site, Washington State Department of Ecology, August 2007.
532	1127	Roland	Washington State Department of Ecology, Manchester Environmental Lab Analysis Report for Black Sand Beach, February, 2008
533	1126	Roland	Upper Columbia River – Black Sand Beach Proposal to Conduct Static Acute Fish Toxicity Tests, March 6, 2008
534	NA	Roland	Summary of Sediment Sampling Activities to Support Preliminary Benthic Invertebrate Colonization Studies of Lake Roosevelt Sediments, Technical Memorandum,
			Toxics Cleanup Program, Washington State Department of Ecology, June 2008
535	NA	Roland	Washington State Department of Ecology Capital Project Request for Upper Columbia River Black Sand Beach Cleanup, August 2008
536	NA	Roland	Email from Flora Goldstein to John Roland re: Ecology past costs for Lake Roosevelt, July 17, 2006.

Trial Exhibit No.	Dep. Exhibit No.	Deponent	Title
537	NA	Roland	Partial Identification of Past Costs for UCR Site by John Roland, Washington State Department of Ecology, June 1, 2012
538	NA	Roland	Estimate of Costs for Upper Columbia/CERCLA RI/FS, Washington State Department of Ecology
539	NA	Roland	Intergovernmental Memorandum of Agreement for the Upper Columbia River Superfund Site, 2007
540	NA	Roland	Estimate of Costs for Upper Columbia/CERCLA RI/FS, Washington State Department of Ecology
541	NA	Roland	Washington State Department of Ecology detail of Expenditures, ECY XJ25
542	NA	Roland	Photos taken by Ecology of Black Sand Beach, 2008-2011
543	NA	Roland	Photos taken by Ecology of Black Sand Beach interim action, 2010
544	101 LMI	Smith	Geoffrey TG Scott Report on Application for Environmental Impairment Liability Insurance with, Scott invoice
545	1458	Stevens	Resume of Jennifer Stevens
546	1401	Tonel	UCR/LK Roosevelt River Mile 597 to 745 Preliminary Assessment Report, by Region 10 START
547	1402	Tonel	Preliminary Assessments and Site Investigations Report, Lower Pend Oreille River Mines and Mills, by Region 10 START-2
548	1404	Tonel	Preliminary Assessments and Site Inspections Report, UCR Mines and Mills, Stevens Co., by Region 10 START-2
549	1405	Tonel	UCR Expanded Site Inspection Report NE WA, by Region 10 START-2
550	1407	Tonel	Letter from Deborah Leblang to Arnold Bakie enclosing PA/SI of the Cleveland Mine and Mill in Stevens Co
551	1409	Tonel	Summary of Contaminant Sources / UCR Site RI/FS
552	1410	Tonel	Email from Tonel to Stone and Passmore re Upper Columbia Mercury Work Plan
553	1 - 1 - 1		Duplicate Exhibit
554			Duplicate Exhibit
555	+		Duplicate Exhibit Duplicate Exhibit
556			Duplicate Exhibit
557	+		Duplicate Exhibit Duplicate Exhibit
558	NA	Vlassopoulos	CCT Expert Blum, Joel\5-11-11 Report\J Blum Docs Considered\CHM100809-3.pdf
559	NA	Vlassopoulos	Reported Metals Concentrations in Trail Smelter Slag, Table 1, page 7, Export Report of Dimitrios Vlassopoulos, September 17, 2010
560	NA	Vlassopoulos	Estimated Cumulative Discharges from the Trail Facility to the Columbia River (1921-2005), Table 2, page, 8, Export Report of Dimitrios Vlassopoulos, September 17,
561	NA	Vlassopoulos	2010 Metals Concentrations in Pre-smelter Sediment and Maximum Detected in Core Samples, Table 3, page 32, Export Report of Dimitrios Vlassopoulos, September 17, 2010
562	NA	Vlassopoulos	Summary of Porewater Chemistry Data, Table 4, page 42, Export Report of Dimitrios Vlassopoulos, September 17, 2010
563	NA	Vlassopoulos	Sediment sample locations used in factor analysis, Figure 1, page 12, Export Report of Dimitrios Vlassopoulos, September 17, 2010
564	NA	Vlassopoulos	Metals loadings on Factor 1 (top), Factor 2 (middle), and Factor 3 (bottom), Figure 2, page 15, Export Report of Dimitrios Vlassopoulos, September 17, 2010
565	NA	Vlassopoulos	Factor 1 scores, Figure 3, page 16, Export Report of Dimitrios Vlassopoulos, September 17, 2010
566	NA	Vlassopoulos	Factor 3 scores, Figure 4, page 17, Export Report of Dimitrios Vlassopoulos, September 17, 2010
567	NA	Vlassopoulos	Pb-206/Pb-204 versus Pb-208/Pb-204 isotope ratio plot showing signatures of regional and smelter-derived lead sources, Figure 5, page 22, Export Report of Dimitrios Vlassopoulos, September 17, 2010
568	NA	Vlassopoulos	Pb-207/Pb-204 versus Pb-208/Pb-204 isotope ratio plot showing signatures of regional and smelter-derived lead sources, Figure 6, page 23, Export Report of Dimitrios Vlassopoulos, September 17, 2010
569	NA	Vlassopoulos	Pb-206/Pb-204 versus Pb-208/Pb-204 isotope ratio plot for UCR sediment samples, Figure 7, page 26, Export Report of Dimitrios Vlassopoulos, September 17, 2010
570	NA	Vlassopoulos	Pb-207/Pb-204 versus Pb-208/Pb-204 isotope ratio plot for UCR sediment samples, Figure 8, page 27, Export Report of Dimitrios Vlassopoulos, September 17, 2010
571	NA	Vlassopoulos	Pb-206/Pb-204 isotope ratio versus slag content of UCR sediment samples and slag separates, Figure 9, page 28, Export Report of Dimitrios Vlassopoulos, September 17, 2010
572	NA	Vlassopoulos	Pb-206/Pb-204 isotope ratio versus River Mile for UCR sediment samples and slag separates, Figure 10, page 29, Export Report of Dimitrios Vlassopoulos, September 17, 2010
573	NA	Vlassopoulos	Pb-206/Pb-204 isotope ratio versus lead concentration of UCR sediment samples, Figure 11, page 30, Export Report of Dimitrios Vlassopoulos, September 17, 2010
574	NA	Vlassopoulos	Concentration profiles of lead, zinc, and copper in three UCR sediment cores in which pre-smelter sediment was encountered, Figure 12, page 31, Export Report of Dimitrios Vlassopoulos, September 17, 2010

Trial Exhibit No.	Dep. Exhibit No.	Deponent	Title
575	NA	Vlassopoulos	Antimony, arsenic, barium, and cadmium concentrations of UCR sediment samples versus Pb-206/Pb-204 isotope ratio. Vertical dashed line indicates upper limit for
			Pb-206/Pb-204 of Trail smelter lead, Figure 13, page 33, Export Report of Dimitrios Vlassopoulos, September 17, 2010
576	NA	Vlassopoulos	Chromium, cobalt, copper, and iron concentrations of UCR sediment samples versus Pb-206/Pb-204 isotope ratio. Vertical dashed line indicates upper limit for Pb-
			206/Pb-204 of Trail smelter lead, Figure 14, page 34, Export Report of Dimitrios Vlassopoulos, September 17, 2010
577	NA	Vlassopoulos	Lead, manganese, mercury, and nickel concentrations of UCR sediment samples versus Pb-206/Pb-204 isotope ratio. Vertical dashed line indicates upper limit for Pb-
F70	110	\/	206/Pb-204 of Trail smelter lead, Figure 15, page 35, Export Report of Dimitrios Vlassopoulos, September 17, 2010
578	NA	Vlassopoulos	Concentration profiles of lead, zinc, and copper in three UCR sediment cores in which pre-smelter sediment was encountered. The horizontal dashed line represents
579	NA	Vlassopoulos	the top of the pre-smelter horizon at these locations, Figure 16, page 36, Export Report of Dimitrios Vlassopoulos, September 17, 2010 Resume of Dimitrios Vlassopoulos, Appendix A, Export Report of Dimitrios Vlassopoulos, September 17, 2010
580	NA	Vlassopoulos	Sediment Core Study, Appendix B, Export Report of Dimitrios Viassopoulos, September 17, 2010
581	NA	Vlassopoulos	FA Loading Results, Appendix C1, Export Report of Dimitrios Vlassopoulos, September 17, 2010
582	NA	Vlassopoulos	FA Scores, Appendix C2, Export Report of Dimitrios Viassopoulos, September 17, 2010
583	NA NA	Vlassopoulos	
584	NA NA	Vlassopoulos	Pb Isotope Compositions and Backscatter Electron Image Analysis, Appendix D, Export Report of Dimitrios Vlassopoulos, September 17, 2010 Pb Isotope Source Data, Appendix D2, Export Report of Dimitrios Vlassopoulos, September 17, 2010
	NA	· ·	
585	NA	Vlassopoulos	Release of Major and Trace Elements from Smelter Slag Separated from the Upper Columbia River, a.k.a. "Slag Metals Release Study", Appendix E, Export Report of
586	NA	Vlassopoulos	Dimitrios Vlassopoulos, September 17, 2010 In Situ Porewater Sampling Study, Appendix F, Export Report of Dimitrios Vlassopoulos, September 17, 2010
587	NA	Vlassopoulos	Cadmium: Total and Dissolved Concentrations in the Columbia River at Waneta and Estimated Percentage Particulate Fraction, Figure 1, page 6, Rebuttal Report of
367	INA	viassopoulos	Dimitrios Vlassopoulos. May 13, 2011
588	NA	Vlassopoulos	Copper: Total and Dissolved Concentrations in the Columbia River at Waneta and Estimated Percentage Particulate Fraction, Figure 2, page 7, Rebuttal Report of
			Dimitrios Vlassopoulos, May 13, 2011
589	NA	Vlassopoulos	Lead: Total and Dissolved Concentrations in the Columbia River at Waneta and Estimated Percentage Particulate Fraction, Figure 3, page 8, Rebuttal Report of
			Dimitrios Vlassopoulos, May 13, 2011
590	NA	Vlassopoulos	Zinc: Total and Dissolved Concentrations in the Columbia River at Waneta and Estimated Percentage Particulate Fraction, Figure 4, page 9, Rebuttal Report of
			Dimitrios Vlassopoulos, May 13, 2011
591	NA	Vlassopoulos	Modeled Seasonal High- And Low-Flow Average Velocity Profiles in the Upper Columbia River After the Grand Coulee Dam Was Built, Figure 5, page 11, Rebuttal
			Report of Dimitrios Vlassopoulos, May 13, 2011
592	NA	Vlassopoulos	Grain-size Distribution of Sediments in the Mid-channel of the Upper Columbia River, Figure 6, page 12, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
593	NA	Vlassopoulos	Factor 1 (Slag) Sample Scores Plotted Against River Mile, Figure 7, page 15, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
594	NA	Vlassopoulos	Factor 2 Sample Scores Plotted Against River Mile, Figure 8, page 15, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
595	NA	Vlassopoulos	Factor 3 (Liquid Effluent) Sample Scores Plotted Against River Mile, Figure 9, page 16, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
596	NA	Vlassopoulos	Factor 1 Scores versus River Mile, Coded by Study, Figure 10, page 19, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
597	NA	Vlassopoulos	Factor 2 Scores versus River Mile, Coded by Study, Figure 11, page 20, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
598	NA	Vlassopoulos	Factor 3 Scores versus River Mile, Coded by Study, Figure 12, page 20, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
599	NA	Vlassopoulos	Variation of Factor 3 Sample Scores with Clay Content of Samples, Figure 13, page 21, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
600	NA	Vlassopoulos	Sampling Locations of Dr. Riese's "Identified Northport/Leroi Slag" Samples Relative to the Former Smelter Site, Figure 14, page 23, Rebuttal Report of Dimitrios
			Vlassopoulos, May 13, 2011
601	NA	Vlassopoulos	Pb-207/Pb-204 versus Pb-206/Pb-204 of Slag Samples, Figure 15, page 24, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
602	NA	Vlassopoulos	Pb-207/Pb-204 versus Pb-208/Pb-204 of Slag Samples, Figure 16, page 26, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
603	NA	Vlassopoulos	Pb-207/Pb-204 versus Pb-208/Pb-204 of Sediment Samples, Figure 17, page 28, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
604	NA	Vlassopoulos	Calculated Solubilities of Magnetite and Zinc Spinel in Water at pH 7 as a Function of Redox Potential (Eh), Figure 18, page 31, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
605	NA	Vlassopoulos	Element Concentrations on Surfaces of Slag Particle Rims and Inner Surfaces Exposed by Removing Rim, Figure 19, page 33, Rebuttal Report of Dimitrios
	<u> </u>		Vlassopoulos, May 13, 2011
606	NA	Vlassopoulos	SEM Image of Slag Particle Showing Discontinuous, Cracked, and Peeling Outer Weathered Layer, Figure 20, page 35, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
607	NA	Vlassopoulos	SEM Image of Trail Slag Particle Showing Discontinuous and Peeling Outer Weathered Layer, Figure 21, page 36, Rebuttal Report of Dimitrios Vlassopoulos, May 13,
		•	2011

Trial Exhibit No.	Dep. Exhibit No.	Deponent	Title
608	NA	Vlassopoulos	SEM Image of Trail Slag Particle, SCB15A, Collected from UCR Sediment Near the International Border, Figure 22, page 37, Rebuttal Report of Dimitrios Vlassopoulos,
800	INA	viassopoulos	May 13. 2011
609	NA	Vlassopoulos	Higher Magnification View of Figure 22 Showing Discontinuous, Cracked, and Peeling Outer Weathered Layer Exposing Pitted Slag Surface Underneath, Figure 23,
			page 38, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
610	NA	Vlassopoulos	Close-up View of Figure 23 Showing Cracked and Peeling Outer Weathered Layer and Pitted Slag Surface Underneath, Figure 24, page 39, Rebuttal Report of
			Dimitrios Vlassopoulos, May 13, 2011
611	NA	Vlassopoulos	SEM Image of Trail Slag Particle, BSB17A-4, from Black Sand Beach Showing Discontinuous and Cracked Nature of the Outer Weathered Layer, Figure 25, page 40,
612	NA	Massanaulas	Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011 Close-Up View of Figure 25 Showing Two Cracked and Peeling Weathered Layers Exposing Slag Underneath, Figure 26, page 41, Rebuttal Report of Dimitrios
612	NA	Vlassopoulos	Vlassopoulos, May 13, 2011
613	NA	Vlassopoulos	Lead Isotope Ratios in Sediment Porewater, Figure 27, page 46, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
614	NA	Vlassopoulos	Metals Loadings on Riese's PCA Component 2, Figure 28, page 51, Rebuttal Report of Dimitrios Vlassopoulos, May 13, 2011
615	NA	Vlassopoulos	Release of Major and Trace Elements from Smelter Slag Separated from the Upper Columbia River in Batch and Fluidized Bed Reactors
616	NA	Vlassopoulos	Cox, et. al., "Vertical Distribution of trace element concentrations and occurrence of metallurgical slag particles in accumulated bed sediments of Lake Roosevelt
010	IVA	Viassopoulos	cox, et. al., Vertical distribution of trace element concentrations and occurrence of metallar star star particles in accumulated sea scaline its of care nossever
617	38	Walden	Research Notebook: Tls. Slag Stockpiling & Environmental Studies
618	39	Walden	Chemistry and Environment Group Monthly Report - April, 1995
619	40	Walden	Cominco Research Project Definition Worksheet
620	41	Walden	Research Report: Leach Tests of Sulfurcrete Samples
621	42	Walden	Cominco Research Project Definition Worksheet
622	44	Walden	Memo from Walden to Mattson: Interium Report - Laboratory Column Leaching of Ferrous Granules
623	45	Walden	Memo from Walden to JRH: Metals Leaching from Ferrous Granules, a Laboratory Column Study
624	46	Walden	FINAL Survival and Water Quality Results of Bioassays on Five Species of Aquatic Organisms Exposed to Slag From Cominco's Trail Operations, by Nener
625	75	Wyton	Memo: Smelter Mercury Balance (Nov. 1983)
626	76	Wyton	Memo: Trail Operations August Sewer Losses Compared to Levels Specified in Pollution Control Permits
627	78	Wyton	File Note from Jaeck: Barren Slag Disposal
628	79	Wyton	Ltr Re: Permit PE/02753 / Trail Slag Disposal
629	80	Wyton	Meeting with Provincial and Federal Government People on Smelting Technology and Associated Issues
630	81	Wyton	Memo: Advancement of Slag Discharge Elimination Deadline
631	82	Wyton	Effluent Management Task Force Mintues of Meeting - 11 September 1992
632	83	Wyton	Ltr Re: Cominco Commitment to a Revised Slag Program
633	84	Wyton	File Note: 07 Performance, Discussion with Carl Johnson, MOELP
634	85	Wyton	Ltr Re: 07 Sewer Action
635	86	Wyton	Memo: III Combined Performance Hg
636	87	Wyton	Amendments to Effluent Permit PE/02753
637	88	Wyton	E-mail Re: Combined II and III Spill This Week
638	89	Wyton	E-mail Re: 07 Sewer Spill March 13
639	93	Wyton	Memo from McCunn: Trail Operation July 1983 Sewer Losses Compared to Levels Specified in Pollution Control Permits
640	94	Wyton	Memo: Trail Operation November 1983 Sewer Losses Compared to Levels Specified in Pollution Control Permits
641	97	Wyton	E-mail re: Aug 23rd MOE meeting, preview to Sept. 13th meeting
642			Deleted Exhibit
643	NA		Slag floating
644	NA		Trail effluent into Columbia River
645	NA		Slag floating in water
646	NA		Slag floating in water
647	NA		Slag across river
648	NA		Black Sand Beach
649	NA		Photo taken 3/13/2001 of North Half Allotment, Colville Reservation, confluence of Kettle River at Marcus Flats, Kettle Falls; spring drawdon

Seablish No. Deponent Title		-	1	
	Trial	Dep.		
1982 photo of Trail Smelter from IE Archives			Deponent	
1927 photo of Trail Smelter from BC Archives				· ·
1927 photo of Trail Smelter from BC Archives				'
1929 photo of Trail Smelter from BC Archives				'
1936 photo of Trail Smelter from BC Archives				'
1938 photo of Trail Smelter from 8C Archives				'
1943 photo of Trail Smelter from BC Archives				· ·
1940 photo of Trail Smelter from BC Archives				'
1953 photo of Trail Smelter from BC Archives				· ·
D McLean Docs Considered/Nelson Report images dated 5.10.11\SEM images\SC815grain#1 slag SEM images\SC815grain#1_imageA-11.jpg D McLean Docs Considered/Nelson Report images dated 5.10.11\SEM images\SC815grain#1 slag SEM images\SC815grain#1_imageC-09.jpg D McLean Docs Considered/Nelson Report images dated 5.10.11\SEM images\SC815grain#1 slag SEM images\SC815grain#1_imageC-09.jpg D McLean Docs Considered/Nelson Report images dated 5.10.11\SEM images\SC815grain#1 slag SEM images\SC815grain#1_imageC-09.jpg D McLean Docs Considered/Nelson Report images dated 5.10.11\SEM images\SC815grain#1 slag SEM images\SC815grain#1_imageC-09.jpg D McLean Docs Considered/Nelson Report images dated 5.10.11\SEM images\SC815grain#2 slag SEM images\S	658	NA		1940 photo of Trail Smelter from BC Archives
NA	659	NA		1953 photo of Trail Smelter from BC Archives
Description	660	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#1 slag SEM images\SCB15grain#1_imageA-11.jpg
Description		NA		
Description	662	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#1 slag SEM images\SCB15grain#1_imageE-03.jpg
Description	663	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#1 slag SEM images\SCB15grain#1_imageF-02.jpg
D McLean Docs Considered (Nelson Report images dated 5.10.11\SEM images\\SSB17A_4 slag SEM images\\SEB17A_4 imageF-05.jpg MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SEM images\\SCB15grain#2 slag SEM images\\SCB15grain#2 imageA-03.jpg D McLean Docs Considered (Nelson Report images dated 5.10.11\SEM images\\SCB15grain#2 slag SEM images\\SCB15grain#2 jmageA-03.jpg MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SEM images\\SCB15grain#2 slag SEM images\\SCB15grain#2 jmageA-03.jpg MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SEM images\\SCB15grain#2 slag SEM images\\SCB15grain#2 jmageC-01.jpg MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SIAg Photomicrograph\\SBB17A slag grain photographs\\SBB17A_4 Sx.pdf MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SIag Photomicrographs\\SBB17A slag grain photographs\\SBB17A_4 Jbx.pdf MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SIag Photomicrographs\\SBB17A slag grain photographs\\SBB17A_4 jby MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SIag Photomicrographs\\SBB17A_slag grain photographs\\SBB17A_4 jby MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SIag Photomicrographs\\SBB17A slag grain photographs\\SBB17A_4 jby MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SIag Photomicrographs\\SBB17A slag grain photomicrograph\\SBB17A_4 jby MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SIag Photomicrographs\\SBB17A slag grain photomicrograph\\SBB17A_4 jby MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SIag Photomicrographs\\SBB17A_slag grain photomicrograph\\SBB17A_4 jby MA D McLean Docs Considered (Nelson Report images dated 5.10.11\SIag Photomicrographs\\SBB17A_slag grain photomicrograph\\SBB17A_slag grain photomicrographs\\SBB17A_slag grain photomicrograph\\SBB17A_slag grain photomicrograph\\SBB17A_slag grain photomicrographs\\SBB17A_slag grain photomicrographs\\SBB17A_slag grai	664	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\BSB17A_4 slag SEM Images\BSB17A_4_imageA-08.jpg
D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#2 slag SEM images\SCB15grain#2 imageA-03.jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#2 slag SEM images\SCB15grain#2 imageA-03.jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#2 slag SEM images\SCB15grain#2 imageA-02.jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#2 slag SEM images\SCB15grain#2 imageC-01.jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 5x.pdf MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 10x.pdf MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 10x.pdf MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 8jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 8jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photomicrograph\BSB17A_4 8jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photomicrograph\BSB17A_4 8jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A_5 slag grain photomicrograph\BSB17A_4 8jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A_5 slag grain photomicrograph\BSB17A_4 8jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A_5 slag grain photomicrograph\BSB17A_4 8jpg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A_5 slag grain photomicrograph\BSB17A_4 8jpg Ma D McLean Docs Considered\Nelson Report images dated	665	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\BSB17A_4 slag SEM Images\BSB17A_4_imageC-03.jpg
December 9, 2010 Decemb	666	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\BSB17A_4 slag SEM Images\BSB17A_4_imageF-05.jpg
D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#2 slag SEM images\SCB15grain#2_imageC-01.jpg D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 5x.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 10x.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 10x.pdf MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 Jipg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 Jipg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 Jipg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photomicrographs\BSB17A_4 Jipg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photomicrographs\BSB17A_4 Jipg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photomicrographs\BSB17A_4 Jipg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photomicrographs\BSB17A_4 Jipg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photomicrographs\BSB17A_4 Jipg MA D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photomicrographs\BSB17A_4 Jipg Ma D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A_14pip Ma D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A_14pip Ma D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A_14pip Ma D McLean Docs Considered\Nels	667	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#2 slag SEM images\SCB15grain#2_imageA-03.jpg
D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 5x.pdf D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 10x.pdf D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 10x.pdf D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A slag grain photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A slag grain photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A slag grain photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A slag grain photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A_8 lpg grain photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A_8 lag grain photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A_8 lag grain photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A_8 lag grain photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A_4 lpjg D McLean Docs Considered(Nelson Report images dated 5.10.11/Slag Photomicrographs\BSB17A_4 lpjg D	668	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#2 slag SEM images\SCB15grain#2_imageB-02.jpg
Description	669	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\SEM Images\SCB15grain#2 slag SEM images\SCB15grain#2_imageC-01.jpg
D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4.jpg D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4B.jpg D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photomicrograph\SCB15_grain#1.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#1.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrograph\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15_grain#2.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrograph\SCB15_grain#2.pdf D McLean Docs Doc	670	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 5x.pdf
D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4B.jpg D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrographs\BSB17A_4B.jpg D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#1.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf Chemical Analyses and Mineralogical Characterization of Fort Shepherd Slag Sample and Pend Oreille River and Tributary Sediment Samples, Hazen Report a, December 9, 2010 Chemical, Mineralogical, and Textural Characterization of Upper Columbia River Sediments, Hazen Report b, December 10, 2010 Fine Sediment Model (Tracer Study), §1.2, page 9, Appendix to Expert Report of J. Bradley, January 14, 2011 Riese Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Zinc Fluxes from UCR Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Deleted Exhibit Deleted Exhibit Deleted Exhibit Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	671	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4 10x.pdf
D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrograph\SCB15 slag grain photomicrograph\SCB15_grain#1.pdf D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrograph\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf Chemical Analyses and Mineralogical Characterization of Fort Shepherd Slag Sample and Pend Oreille River and Tributary Sediment Samples, Hazen Report a, December 9, 2010 Chemical, Mineralogical, and Textural Characterization of Upper Columbia River Sediments, Hazen Report b, December 10, 2010 Fine Sediment Model (Tracer Study), §1.2, page 9, Appendix to Expert Report of J. Bradley, January 14, 2011 Duplicate Exhibit Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Zinc Fluxes from UCR Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Deleted Exhibit AN Deleted Exhibit Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	672	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4.jpg
D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15_grain#2.pdf Chemical Analyses and Mineralogical Characterization of Fort Shepherd Slag Sample and Pend Oreille River and Tributary Sediment Samples, Hazen Report a, December 9, 2010 Chemical, Mineralogical, and Textural Characterization of Upper Columbia River Sediments, Hazen Report b, December 10, 2010 Bradley Fine Sediment Model (Tracer Study), §1.2, page 9, Appendix to Expert Report of J. Bradley, January 14, 2011 Bradley Duplicate Exhibit Riese Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Zinc Fluxes from UCR Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Deleted Exhibit Deleted Exhibit Deleted Exhibit NA Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	673	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\BSB17A slag grain photographs\BSB17A_4B.jpg
Chemical Analyses and Mineralogical Characterization of Fort Shepherd Slag Sample and Pend Oreille River and Tributary Sediment Samples, Hazen Report a, December 9, 2010 Chemical, Mineralogical, and Textural Characterization of Upper Columbia River Sediments, Hazen Report b, December 10, 2010 Fine Sediment Model (Tracer Study), §1.2, page 9, Appendix to Expert Report of J. Bradley, January 14, 2011 Duplicate Exhibit Riese Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Zinc Fluxes from UCR Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Deleted Exhibit NA Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	674	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrographs\SCB15 slag grain photomicrograph\SCB15 grain#1.pdf
December 9, 2010 Chemical, Mineralogical, and Textural Characterization of Upper Columbia River Sediments, Hazen Report b, December 10, 2010 Fine Sediment Model (Tracer Study), §1.2, page 9, Appendix to Expert Report of J. Bradley, January 14, 2011 Duplicate Exhibit Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Zinc Fluxes from UCR Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Deleted Exhibit Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	675	NA		D McLean Docs Considered\Nelson Report images dated 5.10.11\Slag Photomicrograph\SCB15 slag grain photomicrograph\SCB15 grain#2.pdf
677 NA Chemical, Mineralogical, and Textural Characterization of Upper Columbia River Sediments, Hazen Report b, December 10, 2010 678 1 Bradley Fine Sediment Model (Tracer Study), §1.2, page 9, Appendix to Expert Report of J. Bradley, January 14, 2011 679 Duplicate Exhibit 680 1 Riese Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 681 1 Riese Zinc Fluxes from UCR Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 682 1 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 683 Deleted Exhibit 684 NA Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) 685 NA MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	676	NA		
Duplicate Exhibit Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Zinc Fluxes from UCR Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Deleted Exhibit NA Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	677	NA		
Duplicate Exhibit Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Zinc Fluxes from UCR Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Deleted Exhibit NA Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	678	1	Bradley	Fine Sediment Model (Tracer Study), §1.2, page 9, Appendix to Expert Report of J. Bradley, January 14, 2011
Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Zinc Fluxes from UCR Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Deleted Exhibit NA Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862			,	
Figure 2 Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 Deleted Exhibit NA Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 NA MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862		1	Riese	Relationships Between Stream Flow Velocity and Particle Size Erosion, Transport and Deposition, Figure 19, page 39, Expert Report of Arthur C. (Sandy) Riese,
682 1 Riese Sediment Metal Diffusion Calculations, Appendix I, Expert Report of Arthur C. (Sandy) Riese, January 14, 2011 683 Deleted Exhibit 684 NA Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 685 NA MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	681	1	Riese	Zinc Fluxes from UCR Sediments, Background Surface Water at Birchbank, and Select Tributaries During 2001, Figure 27, page 47, Expert Report of Arthur C. (Sandy)
Deleted Exhibit Potential impact of mercury discharged to Columbia River (prepared for Cominco, Ltd. Attn. Nigel Doyle, by Division of Applied Biology, B.C. Research) TECK 0310648 MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	682	1	Riese	
TECK 0310648 NA MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	683			
685 NA MEMO TO FILE Summary of PCB Meeting re. Future Plant Sewers (J.B. Brodie, Industrial Division Mining Section) TECK0115862	684	NA		
686 NA Higginson Expert Report, Opinion 1 (excerpt)	685	NA		
	686	NA		Higginson Expert Report, Opinion 1 (excerpt)